

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CC4/ASM20006642/4993

ASSIGNMENT

From:

Date:

Estimated Cost:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

N/S	O/S
☒	☒

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs: 12 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

3881

Veh No:

SMR3622L

Yr Regn:

1219

Type: ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

(M)

Make:

Honda Fit.

c.c

1317

Colour

Purple

A/C: Insured / Std / NI / NA

Sp. Reading

52712

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

GK33421827

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ☒ Inorder / Jammed / Leaked / Burnt orBrake: ☒ Inorder / Jammed / Leaked / Burnt orModi: ☒ Nil / STD A/Rim or

Tyre Size:

F:

175/70R14

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

7

Rear

7

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

23/6/20

D.O.I.

24/6/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The ☒ U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

have GIP 17A36554 net 12446
have v. des at folder
Repairer not agree 502

28/7/20 d/s @ 21.000 confirmed v. l. Alin.

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) \$ + RS. SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I.: (\$

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

FASTECH AUTO PTE LTD
1 KAKI BUKIT AVE 6 #01-48
SINGAPORE 417883

VEHICLE No: SMR 3622L

not Authorized
N/A
24/6/20
L/S @ 21,000?
12 days

1PC	FRONT BUMPER	517.70
1PC	FRONT BUMPER TOW COVER	
1PC	FRONT BUMPER FOG LAMP COVER O/S	115.20
1PC	FRONT BUMPER SPONGE	
1PC	FRONT BUMPER REINFORCEMENT	
2PCS	FRONT BUMPER SIDE RETAINERS @ \$20.50	
1SET	FRONT BUMPER CLIPS	
2PCS	FRONT BUMPER PDC SENSORS @ \$195.00	
1PC	FRONT BUMPER CENTRE GARNISH	145.50
1PC	FRONT GRILLE	302.40
1PC	FRONT GRILLE OUTER CHROME	
1PC	FRONT GRILLE 'H' LOGO	
2PCS	HEADLAMPS @ \$1850.00	1170.60
2PCS	HEADLAMP LOWER BRACKETS @ \$65.00	
1PC	FRONT SUPPORT PANEL	
1PC	BONNET	551.50
2PCS	BONNET HINGES \$85.00	
1PC	BONNET RUBBER	
1PC	FRONT FENDER O/S	408.90
1PC	FRONT FENDER INNER PANEL O/S	415.20
1PC	FRONT FENDER INNER ARCH PANEL O/S	288.50
1PC	FRONT FENDER INNER SHIELD O/S	
1SET	FRONT FENDER INNER SHIELD CLIPS O/S	
1PC	WASHER TANK	188.30
1PC	WASHER TANK MOTOR	166.20
1PC	ABS PUMP	2480.20
1PC	FRONT SHOCK ABSORBER O/S	366.20
1PC	FRONT LOWER ARM O/S	395.00
1PC	FRONT DRIVE SHAFT O/S	
1PC	FRONT KNUCKLE ARM O/S	505.20
1PC	FRONT KNUCKLE ARM BEARING O/S	188.30
1PC	FRONT STEERING RACK ASSY	
1PC	FRONT DOOR O/S	845.20
1PC	FRONT DOOR HINGE LOWER O/S	99.20
1PC	FRONT DOOR CHECKER O/S	
1PC	FRONT DOOR MIRROR ASSY O/S	
1PC	FRONT DOOR TRIM O/S	488.50
1PC	FRONT DOOR GLASS REGULATOR O/S	
1PC	FRONT DOOR GLASS REGULATOR MOTOR O/S	
1PC	FRONT DOOR GLASS OUTER MOULDING O/S	
1PC	FRONT DOOR OUTER PILLAR O/S	
1PC	FRONT DOOR OUTER HANDLE O/S	
1PC	FRONT DOOR INNER LOCK O/S	

Dis	\$715.20
11	\$30.00 X
Mrs	\$185.00
NS	\$112.00 X
11	\$311.30 X
o/scre	\$41.00 1PC
11	\$35.00
11	\$390.00 X
To. n	\$185.40
CNA	\$481.20
11	\$366.50 X
11	\$38.00 *
N/San	o/s cra \$3,700.00 1PC
CNA	\$130.00
11	\$515.20 X
11/3uc	\$866.20
11	\$170.00 X
11	\$32.00
Dis	\$566.20
Dis	\$466.30
Dis	\$311.20
To. n	\$165.40
11	\$35.00
Dis	\$199.30
CNA	\$205.00
CNA	\$2,685.50
Bent	\$455.30
Buc	\$422.30
11	\$1,455.20 X
Bent	\$550.30
11	\$250.00
Suc	\$1,885.30 X
Bod. n	\$966.20
Bent	\$105.00
To. n	\$112.00
o/s/scrp	\$485.50
o/s/scrp	\$615.30
Bent	\$245.00
To. n	\$395.20
11	\$86.60 X
R	\$699.20 X
11	\$245.50 X
ym/shuld	\$285.30

11578.7

1PC	FRONT DOOR FRAME BLACK STICKER O/S	nu	\$60.00	✓
1PC	FRONT DOOR INNER RUBBER O/S 118.20	nu	\$125.30	✓
1PC	CENTRE PILLAR O/S 611.30	DOO/Seat	\$615.30	✓
1PC	REAR DOOR O/S 805.20	Goodly DO	\$845.00	✓
1PC	REAR DOOR FRAME BLACK STICKER O/S	nu	\$60.00	✓
1PC	REAR DOOR OUTER HANDLE O/S	11	\$245.30	X
1PC	REAR DOOR GLASS REGULATOR O/S	Seat	\$245.00	✓
1PC	REAR DOOR GLASS REGULATOR MOTOR O/S	Jim	\$392.00	✓
1PC	REAR DOOR HINGE LOWER O/S 89.20	Seat	\$105.00	✓
1PC	REAR DOOR CHECKER O/S	twi	\$112.00	✓
1PC	REAR DOOR INNER TRIM BOARD O/S 480.20	del/orn	\$605.20	✓
1PC	REAR DOOR INNER RUBBER O/S	7.11	\$122.30	✓
1PC	REAR FENDER O/S 845.20	301500/Seat	\$981.20	✓
1PC	REAR FENDER GLASS O/S	11	\$450.00	X
1PC	REAR BUMPER 545.20	To.11	\$715.20	✓
1PC	REAR BUMPER SIDE RETAINER O/S	Seat	\$20.50	✓
1SET	REAR BUMPER CLIPS	nu	\$35.00	✓
2PCS	REAR SHOCK ABSORBERS @\$305.00 228.50	ndstwi	\$610.00	1PC
1PC	REAR AXLE BEAM 1855.30	Seat/ty	\$2,445.00	✓
2PCS	REAR WHEEL HUB BEARINGS @\$680.00 450	N/S	\$1,360.00	1PC
2PCS	REAR WHEEL HUB CAPS @\$150.00	cu7	\$300.00	✓
2PCS	FRONT WHEEL HUB CAPS @\$150.00	0/5cu7	\$300.00	1PC
1PC	FRONT IMPACT SENSOR O/S	Cpe	\$245.00	✓
1PC	DRIVER AIR BAG 1802.30	Activated	\$1,886.20	✓
1PC	DRIVER AIR BAG SPIRAL SENSOR 188.20	Activated	\$311.20	✓
1PC	PASSENGER AIR BAG 2245.30	Activated	\$3,220.20	✓
1PC	DASHBOARD 850.20	To.11	\$1,645.30	✓
2PCS	FRONT SEAT BELTS @\$815.00 645.30 x 2 = 1290.60	Activated	\$1,630.00	✓
1PC	AIR BAG CONTROL UNIT 1188.20	Activated	\$1,560.00	✓
1PC	AIR CON CONDENSER	11	\$966.00	X
1PC	RADIATOR	11	\$1,685.00	X
1PC	ENGINE MOUNTING O/S	8u	\$320.00	X

\$46,415.60

26923.40
20%
21538.72

S.NETT

1PC	FRONT TYRE O/S	cu7	\$200.00	70% = 140
1PC	FRONT STEEL RIM O/S	cu7	\$150.00	80
2PCS	REAR STEEL RIMS @\$150.00	cu7/Seat	\$300.00	80 x 2 = 160
1PC	REAR FENDER GALSS SEALANT O/S	nu	\$50.00	40
1PC	FRONT WINDSCREEN SEALANT	11	\$50.00	X

TO CHECK WIRING	\$80.00	30
TO DISMANTLE & REPLACED PDC SENSOR	\$80.00	40
TO CONDUCT WHEEL ALIGNMENT	\$150.00	80
TO DISMANTLE & REPLACED FRONT UNDER CARRIAGE	\$300.00	120
TO DISMANTLE & REPLACED REAR UNDER CARRIAGE	\$380.00	280
TO REFILL AIR CON GAS	\$120.00	X
TO TRANSFER O/S DOOR MECHANISM	\$120.00	120

TO DISMANTLE & REFIX CUSHION UPHOLSTERY	\$120.00	80
TO DISMANTLE & REFIX REAR FENDER GLASS O/S	\$100.00	100
TO DISMANTLE & REPLACED DASHBOARD	\$380.00	250
TO DISMANTLE & REPLACED AIR BAG	\$350.00	300
TO REPROGRAMME AIR BAG SYSTEM	\$350.00	
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$3,000.00	2000
TO PUTTY & SPRAY PAINTING	\$2,800.00	1600
TOTAL	\$55,495.60	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P - 21538.72
~~P - 13465.70~~
 S.N - 420.00
 L - 4970.00

~~18857.70~~
 26928.72
 252

 21547.97