

SIN FATT DIESEL MOTOR

Block 3020A Ubi Road 1 # 01-33 Singapore 408714

HP: 92712214

Business Reg. No : 377435/00K

25th JUNE 2020

WTC M&E PTE LTD
BLOCK 3020A UBI ROAD 1
01-33
Singapore 408714

VM20100978

TPMS LG.
Vonne

Accident date: 24th JUNE 2020

Estimated repair cost for vehicle no: GBG3994B NISSAN NV200 1.6 (A) '17

S/n	Qty	Items	U/price	Amount
				\$958.20 ✓ 858
1	1	Front Bonnet <i>cracked</i>		\$85.20 x
2	1	Front Bonnet Lock <i>3 new</i>		\$112.20 x
3	1	Front Bonnet Lock Panel		\$824.40 ✓
4	2	Front Head Lamp <i>cracked</i>	\$412.20	\$135.20 x
5	2	Front Head Lamp Lower Bracket <i>new for new</i>	\$67.60	\$697.20 348.60
6	2	Front Head Lamp Lower Cover <i>new</i>	\$348.60	\$90.40 x
7	2	Front Head Lamp Lower Cover Side Bracket <i>3 new</i>	\$45.20	\$44.00 x
8	8	Front Head Lamp Lower Cover Clips	\$5.50	\$612.20 ✓
9	1	Front Bumper <i>del</i>		\$20.80 ✓
10	8	Front bumper clips <i>new</i>	\$2.60	\$96.40 ✓
11	2	Front Bumper Side Bracket <i>new</i>	\$48.20	\$50.00 ✓
12	1	Front Bumper Number Plate <i>Best</i>		\$65.00 30
13	10	Front Bumper Clips <i>new</i>	\$6.50	\$280.70 107.20
14	1	Front Bumper Inner Sponge <i>cracked</i>		\$591.90 ✓
15	1	Front Bumper Reinforcement <i>Best</i>		\$295.70 x
16	1	Front Support Panel Top <i>3 new</i>		\$253.50 x
17	1	Front Support Panel Lower		\$92.00 46.50
18	2	Front Support Panel Side Cover <i>new</i>	\$46.30	\$65.00 10
19	10	Front Support Panel Side Cover Clips <i>new</i>	\$6.50	\$299.20 ✓
20	1	Front Grille <i>new</i>		\$55.20 ✓
21	1	Front Grille Emblem Logo <i>new</i>		\$44.00 20
22	8	Front Grille Clips <i>new</i>	\$5.50	\$220.00 x
23	1	water pump <i>new</i>		\$596.30 x
24	1	Front Radiator <i>3 new</i>		\$661.20 x
25	1	Front Air-Con Condenser <i>new</i>		\$2,250.00 1724.60
26	1	Rear Boot Lid <i>Distorted</i>		\$152.20 ✓
27	1	Rear Boot Lid Inner Lock <i>Tanned</i>		\$77.40 ✓
28	1	Rear Boot Lid <i>new</i> NV200 Logo		\$215.20 x
29	1	Rear Boot Lid Center Moulding <i>3 new</i>		\$55.00 x
30	10	Rear Boot Lid <i>new</i> Inner Trim Board Clips	\$0.00	\$143.60 ✓
31	1	Rear Boot Lid Inner Rubber <i>new</i>		\$35.20 ✓
32	1	Rear Boot Lid <i>new</i> Logo		\$300.00 200 (SV)
33	1	Rear Bumper Reverse Sensor-set <i>Damaged</i>		\$30.00 10 (SV)
34	1	Rear Boot Lid <i>new</i> 70KM/H Logo		\$262.40 x
35	2	Rear Boot Lid <i>new</i> Hinge	\$131.20	\$112.00 ✓
36	1	Rear Boot Lid Windscreen Seal <i>new</i>		\$512.20 ✓
37	1	Rear Bumper <i>del</i>		\$70.40 ✓
38	2	Rear Bumper Side Bracket <i>new</i>	\$35.20	\$65.00 30
39	10	Rear Bumper Clips <i>new</i>	\$6.50	\$125.20 ✓
40	1	Rear Bumper Inner Sponge <i>cracked</i>		\$285.20 ✓
41	1	Rear End Panel Outer <i>Distorted</i>		\$841.80 572
42	1	Rear End Panel Inner <i>Distorted</i>		\$55.50 ✓
43	1	Rear End Panel Top Garnish <i>cracked</i>		\$1,353.40 x
44	1	Rear Floor Panel <i>Repair</i>		

45 2 Rear Tail Lamp *Rit Cooled* \$315.20
 46 1 Rear Spare Tyre Bracket *Not Nec*
 47 1 Rear Exhaust *Not Nec*

~~\$630.40~~ 315.20
~~\$212.70~~ X
~~\$825.00~~ X

8180 90 SN 210
 7362 81

Subtotal :-

\$15,856.30

Labour charges

To remove & refit reverse sensor

To remove & refit rear windscreen

Gum

To remove & refix rear exhaust

to Remove & Refix upholstery

Gum

To remove & re-fix front air-con condenser,
 Radiator & top up gas

To Check Wiring

Tuff kote

Panel beating

Spray painting

To remove and refit boot lid fittings.

~~\$100.00~~ 50

~~\$150.00~~ 120

\$50.00 ✓

\$180.00 X

~~\$120.00~~ X, 80

\$50.00 X

\$250.00 X

\$60.00 ✓

~~\$150.00~~ 80

~~\$1900.00~~ 1600

~~\$1,600.00~~ 1300

3420

~~150~~ 80
 Subtotal :-

Total:-

\$4,310.00

\$20,166.30

L/S 26/06/20

10 Days.

total: 10992.81

L/S 8.8K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:.