

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jowyn Tay Mei Ling

Date: 21 Jul 2020

Preliminary Advice

Insured Vehicle No	: GBE1210D	Accident Date	: 24/06/2020
TP Vehicle No	: GBG3994B	Assignment Date	: 24/06/2020
Make	: NISSAN NV200	Est. Duration of Repair	: 10
Date of Inspection	: 26/06/2020		
Inspection At	: SIN FATT DIESEL MOTOR (HQ) BLK 3020A #01-33 UBI ROAD 1 SINGAPORE 408714		

Point of Impact / General Description of Damages

The vehicle is sustained impact / damage front and rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	20,166.30
Revised Amount	:S\$	10,992.81
Check Items (Estimated)	:S\$	0.00
Total	:S\$	10,992.81

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical for repair
- () The vehicle is not economical for repair
- () Part-by-Part repair
- () Lump Sum repair

- (X) The above survey was conducted on a 'without prejudice' basis.