

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
 4 Shenton Way
 #21-01 SGX Centre 2
 Singapore 068807

From: LKK Auto Consultants Pte Ltd
 51 Ubi Ave 1 #01-25
 Paya Ubi Industrial Park
 Singapore 408933

Attn: Chhia Nyuk Pui Date: 02 Jul 2020

Preliminary Advice

Insured Vehicle No	:	SLV1914Z		
TP Vehicle No	:	SLC2292C	Accident Date	: 23/06/2020
Make	:	HONDA VEZEL	Assignment Date	: 25/06/2020
Date of Inspection	:	25/06/2020	Est. Duration of Repair	: 6
Inspection At	:	IMPERIUM AUTOMOTIVE - KAKI BUKIT (HQ) 25 KAKI BUKIT ROAD 4, #01-49 SYNERGY@KB SINGAPORE 417800		

Point of Impact / General Description of Damages

The vehicle sustained damages at the rear portion.

Repairer's Estimate (Gross)	:	S\$ 16,080.92
Revised Amount	:	S\$ 8,522.20
Check Items (Estimated)	:	S\$ 0.00
Total	:	S\$ 8,522.20
Lump Sum Repair :S\$ 6,800.00		

Total Loss Consideration

New for Old Value	:	S\$
Pre-Accident Value	:	S\$
COE / PARF Rebate	:	S\$
Salvage Value	:	S\$
Margin for Repair	:	S\$

Remarks

- () The vehicle is economical for repair
 - () The vehicle is not economical for repair
 - () Part-by-Part repair
 - (X) Lump Sum repair
- (X) The above survey was conducted on a 'without prejudice' basis.