

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20006658/KDA3Q2

Date: 19/08/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100349134

Claimant
Vehicle No : SKK598D **Insured Vehicle No :** SBY981M

Date of Loss: 23/06/2020 Nature of Claim: TP Claim No: 4662150327SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKK598D		
Make & Model:	BMW 520I, 2.0 D/AB 2WD 4DR GAS/D NAV (A)	Engine No:	A5530433N20B20B
Reg. Date:	05/06/2013 (Man. Year: 2013)	Chassis No:	WBAXG120X0DX53036
Colour:	Metallic Black	Odometer:	143409 km
Engine Capacity:	1997 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55 R17	Rear Tyre Size:	225/55 R17
Front Left Side:	Michelin 7 mm	Rear Left Side:	Michelin 7 mm
Front Right Side:	Michelin 7 mm	Rear Right Side:	Michelin 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	25,451.20	2,885.98	22,565.22	88.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,750.00	1,450.00	2,300.00	61.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	29,201.20	4,335.98	24,865.22	85.15
Approved Total (Overridden) (S\$)		3,450.00		
(S\$)	29,201.20	3,450.00	25,751.20	88.19
+ GST 7.00/7.00% (S\$)	2,044.08	241.50	1,802.58	88.19
Nett Amount (S\$)	31,245.28	3,691.50	27,553.78	88.19
+ Car Rental (6.0 x S\$150.00/day + 7.00% GST) (S\$)		963.00		
+ Doc/Search Fee (S\$)		31.00		
Nett Liability (S\$)		4,685.50		

INSPECTION

Date of Assignment: 25/06/2020

Date Inspected: 29/06/2020 Inspected At:

MBM Wheelpower Pte Ltd (Sin Ming)
176 Sin Ming Drive #01-15, Sin Ming
AutoCare
Singapore 575721

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG**Manager:** CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Repair	2,700.00 FL	*- FL
2	1		*FRONT BUMPER	Mtg Cracked	1,800.00 FL	*1,345.30 FL
3	6		*FRONT BUMPER SCREW	Necessary	30.00 FL	*30.00 FL
4	6		*FRONT BUMPER C-CLIP NUT	Necessary	24.00 FL	*24.00 FL
5	2		*FRONT BUMPER EXPANSION RIVET	Necessary	4.00 FL	*4.00 FL
6	1		*FRONT BUMPER TOWING COVER	Serviceable	50.00 FL	*- FL
7	4		*FRONT BUMPER SENSOR	Serviceable	800.00 FL	*- FL
8	1		*FRONT BUMPER REINFORCEMENT	Repair	850.00 FL	*- FL
9	1		*FRONT BUMPER SPONGE	Serviceable	80.00 FL	*- FL
10	1		*FRONT BUMPER RETAINER LH	Serviceable	90.00 FL	*- FL
11	1		*FRONT BUMPER RETAINER RH	Serviceable	90.00 FL	*- FL
12	1		*FRONT BUMPER BMW DECAL	Serviceable	120.00 FL	*- FL
13	1		*FRONT GRILLE MIDDLE	Serviceable	100.00 FL	*- FL
14	1		*FRONT GRILLE RH	Serviceable	120.00 FL	*- FL
15	1		*FRONT GRILLE LH	Serviceable	120.00 FL	*- FL
16	1		*FRONT FINISHER ROD ,LH	Serviceable	60.00 FL	*- FL
17	1		*FRONT FINISHER ROD ,RH	Serviceable	60.00 FL	*- FL
18	1		*FRONT GRILLE SUPPORT	Serviceable	30.00 FL	*- FL
19	1		*HEADLIGHT LH	Serviceable	2,900.00 FL	*- FL
20	1		*HEADLIGHT RH	Serviceable	2,900.00 FL	*- FL
21	1		*FOG LIGHT LH	Serviceable	320.00 FL	*- FL
22	1		*FOG LIGHT RH	Serviceable	320.00 FL	*- FL
23	1		*RADIATOR	Serviceable	1,100.00 FL	*- FL
24	1		*RADIATOR CARRIER LH	Serviceable	100.00 FL	*- FL
25	1		*RADIATOR CARRIER RH	Serviceable	110.00 FL	*- FL
26	1		*RADIATOR COVER	Serviceable	90.00 FL	*- FL
27	1		*AIRCON COMPRESSOR	Not Necessary	4,000.00 FL	*- FL
28	1		*BOOT	Repair	2,200.00 FL	*- FL
29	1		*REAR BUMPER	Buckled	2,000.00 FL	*1,563.35 FL
30	1		*REAR BUMPER GUIDE ,CENTRE REAR	Serviceable	150.00 FL	*- FL
31	1		*REAR BUMPER MOUNT ,REAR LEFT	Serviceable	200.00 FL	*- FL
32	1		*REAR BUMPER MOUNT ,REAR RIGHT	Serviceable	200.00 FL	*- FL
33	1		*REAR BUMPER GUIDE ,BOTTOM CENTRE	Serviceable	120.00 FL	*- FL
34	4		*REAR BUMPER SENSOR	Serviceable	800.00 FL	*- FL
35	10		*REAR BUMPER RIVET	Necessary	50.00 FL	*50.00 FL
36	1		*REAR BUMPER TOWING COVER	Serviceable	100.00 FL	*- FL
37	1		*REAR BUMPER BMW DECAL	Necessary	140.00 FL	*140.00 FL
38	1		*REAR BUMPER REFLECTOR LH	Serviceable	70.00 FL	*- FL
39	1		*REAR BUMPER REFLECTOR RH	Serviceable	70.00 FL	*- FL
40	1		*REAR LIGHT IN THE SIDE PANEL LH	Serviceable	900.00 FL	*- FL
41	1		*REAR LIGHT IN THE SIDE PANEL RH	Serviceable	800.00 FL	*- FL
42	1		*REAR LIGHT IN TRUNK LID LH	Serviceable	700.00 FL	*- FL
43	1		*REAR LIGHT IN TRUNK LID RH	Serviceable	700.00 FL	*- FL
44	1		*NUMBER PLATE & HOLDER	Bent	50.00 FS	*45.00 FS
45	1		*BODY SEALANT	Not Necessary	50.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	28,268.00	3,201.65
- List Item Discount on L Items 10.00/10.00% (\$\$)	2,816.80	315.67
Total Parts (\$\$)	25,451.20	2,885.98

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ,REFIT & REPAIR AFFECTED DAMAGED PARTS .INCLUDING TO KNOCK -OUT ,WELD & STRAIGHTEN ON THE AFFECTED PARTS	New	1,600.00	600.00
2	TO REMOVE,REFIT & UPHOLSTERY TO FACILITATE REPAIRS	New	200.00	0.00
3	TO CHECK & RECONNECT ALL NECESSARY WIRING	New	100.00	40.00
4	TO REMOVE & REFIT ALL SENSOR	New	100.00	60.00
5	TO RESET ENGINE WARNING LIGHT (ABS ,SRS ,ECU MEMORY & ETC)	New	250.00	0.00
6	TO SPRAY PAINT ON THE AFFECTED AREAS	New	1,500.00	750.00
Gross Labour Cost (\$)			3,750.00	1,450.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >