



MBM WHEELPOWER PTE. LTD.

YOUR REF.: SBY981M

OUR REF.: SKK598D

TO: ~~NTUC INCOME~~
ATG Insurance
CC: MOTOR CLAIMS DEPARTMENT

FAX:

Not Withheld
Clamp 87
Pruning after Rain
5 days

DATE: 24/6/2020
FROM: Lee Shirley
FAX: 64525333
CONTACT: 86865188
MAKE & MODEL: BMW 520i AT D/AB 2WD 4DR
CHASSIS NO.: WBAXG120X0DX53036
ENGINE NO.: A5530433N20B20B
YEAR MADE: 2013
ACCIDENT DATE: 23 June 2020

ESTIMATE FOR VEHICLE NO.: SKK598D

NO.	DESCRIPTION	PART NO.	QTY.	LIST PRICE
1	BONNET		1	\$ 2,700.00 X
2	FRONT BUMPER		1	\$ 1,800.00 ?
3	FRONT BUMPER SCREW		6	\$ 30.00 ?
4	FRONT BUMPER C-CLIP NUT		6	\$ 24.00 ?
5	FRONT BUMPER EXPANSION RIVET		2	\$ 4.00 ?
6	FRONT BUMPER TOWING COVER		1	\$ 50.00 X
7	FRONT BUMPER SENSOR		4	\$ 800.00 X
8	FRONT BUMPER REINFORCEMENT		1	\$ 850.00 ?
9	FRONT BUMPER SPONGE		1	\$ 80.00 ?
10	FRONT BUMPER RETAINER LH		1	\$ 90.00 X
11	FRONT BUMPER RETAINER RH		1	\$ 90.00 X
12	FRONT BUMPER " BMW " DECAL		1	\$ 120.00 X
13	FRONT GRILLE MIDDLE		1	\$ 100.00 X
14	FRONT GRILLE RH		1	\$ 120.00 X
15	FRONT GRILLE LH		1	\$ 120.00 X
16	FRONT FINISHER ROD , LH		1	\$ 60.00 X
17	FRONT FINISHER ROD , RH		1	\$ 60.00 X
18	FRONT GRILLE SUPPORT		1	\$ 30.00 X
19	HEADLIGHT LH		1	\$ 2,900.00 ?
20	HEADLIGHT RH		1	\$ 2,900.00 ?
21	FOG LIGHT LH		1	\$ 320.00 X
22	FOG LIGHT RH		1	\$ 320.00 X
23	RADIATOR		1	\$ 1,100.00 X
24	RADIATOR CARRIER LH		1	\$ 100.00 X
25	RADIATOR CARRIER RH		1	\$ 110.00 X
26	RADIATOR COVER		1	\$ 90.00 ?
27	AIRCON COMPRESSOR		1	\$ 4,000.00 X

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

MBM WHEELPOWER PTE. LTD.
160 SIN MING DRIVE, #06-02
SIN MING AUTOCITY
T 6262 8888 F 6452 5333
COMPANY REG. NO.: 200204110W

28	BOOT	1	\$	<i>Rn</i>	2,200.00 <i>X</i>
29	REAR BUMPER	1	\$	<i>Rn</i>	2,000.00 <i>X</i>
30	REAR BUMPER Guide, centre rear	1	\$		150.00 <i>X</i>
31	REAR BUMPER Mount, rear left	1	\$		200.00 <i>X</i>
32	REAR BUMPER Mount, rear right	1	\$		200.00 <i>X</i>
33	REAR BUMPER Guide, bottom centre	1	\$		120.00 <i>X</i>
34	REAR BUMPER SENSOR	4	\$		800.00 <i>X</i>
35	REAR BUMPER RIVET	10	\$	<i>Rn</i>	50.00 <i>X</i>
36	REAR BUMPER TOWING COVER	1	\$	<i>Rn</i>	100.00 <i>X</i>
37	REAR BUMPER "BMW" DECAL	1	\$	<i>Rn</i>	140.00 <i>X</i>
38	REAR BUMPER REFLECTOR LH	1	\$	<i>Rn</i>	70.00 <i>X</i>
39	REAR BUMPER REFLECTOR RH	1	\$	<i>Rn</i>	70.00 <i>X</i>
40	REAR LIGHT IN THE SIDE PANEL LH	1	\$	<i>Rn</i>	900.00 <i>X</i>
41	REAR LIGHT IN THE SIDE PANEL RH	1	\$	<i>Rn</i>	800.00 <i>X</i>
42	REAR LIGHT IN TRUNK LID LH	1	\$	<i>Rn</i>	700.00 <i>X</i>
43	REAR LIGHT IN TRUNK LID RH	1	\$	<i>Rn</i>	700.00 <i>X</i>
TOTAL:			\$		28,168.00
LESS 10%:			\$		(2,816.80)
PARTS TOTAL:			\$		25,351.20

SPECIAL NETT

NUMBER PLATE & HOLDER
BODY SEALANT

1	\$	<i>Bj</i>	50.00
1	\$	<i>Rn</i>	50.00 <i>X</i>

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS, INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS
TO REMOVE, REFIT & UPHOLSTERY TO FACILITATE REPAIRS
TO CHECK & RECONNECT ALL NECESSARY WIRING
TO REMOVE & REFIT ALL SENSOR
TO RESET ENGINE WARNING LIGHT (ABS, SRS, ECU MEMORY & ETC)
TO SPRAY PAINT ON THE AFFECTED AREAS

	\$	<i>600</i>	1,600.00
	\$	<i>Rn</i>	200.00 <i>X</i>
	\$	<i>40</i>	100.00
	\$	<i>60</i>	100.00
	\$		250.00 <i>X</i>
	\$	<i>750</i>	1,500.00

TOTAL:	\$	29,201.20
7% GST:	\$	2,044.08
GRAND TOTAL:	\$	31,245.28

MBM WHEELPOWER PTE. LTD.
160 SIN MING DRIVE, #08-02
SIN MING AUTOCITY
TEL: 6262 8888 / 6452 5533
COMPANY REG. NO. 200504110V