

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

23/06/2020

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

TPAXA

Xiao Tony

Accident date: 23-06-2020

Estimated repair cost for vehicle no: SMH8860K HONDA FIT HYBRID 1.5 19'

CHASSIS: GP51330682

S/N	QTY	ITEMS	U/PRICE	AMOUNT	
1	1	Rear Boot Lid <i>Deletd</i>		<i>880.40</i> \$955.00	✓
2	2	Rear Boot Lid Hinge <i>2 per</i>	\$49.80	\$99.60	+
3	2	Rear Boot Lid Shock Absorber	\$131.80	\$263.60	+
4	1	Rear Boot Lid Chrome Moulding <i>Curled</i>		\$270.50	✓
5	1	Rear Boot Lid Reverse Camera (Special Nett) <i>Net Net</i>		\$680.00	+
6	1	Rear Boot Lid Numper Plate <i>Net</i>		\$50.00	x
7	1	Rear Boot Lid Emblem Logo <i>2 per</i>		\$28.80	✓
8	1	Rear Boot Lid Fit Log		\$35.00	-
9	1	Rear Boot Lid Hybrid Logo		\$38.00	✓
10	1	Rear Boot Lid Lock <i>Demd</i>		\$158.80	✓
11	1	Rear Boot Lid Weatherstrip <i>2 per</i>		\$95.60	x
12	1	Rear Boot Lid Inner Trim Board <i>2 per</i>		\$120.20	x
13	10	Rear Boot Lid Inner Trim Board Clip <i>per</i>	\$6.50	\$65.00	+
14	2	Rear Taillamp <i>HL curled</i>	\$244.60	\$489.20	244.60
15	2	Rear Taillamp Panel <i>Net</i>	\$75.30	\$150.60	+
16	12	Rear Taillamp Clip <i>per</i>	\$6.50	\$78.00	10
17	1	Rear Bumper <i>Deletd</i>		<i>548</i> \$693.70	✓
18	2	Rear Bumper Side Retainer <i>Net</i>	\$27.00	\$54.00	+
19	2	Rear Bumper Reverse Sensor <i>Net</i>	\$380.00	\$760.00	+
20	2	Rear Bumper Side Reflector <i>Net</i>	\$45.00	\$90.00	+
21	1	Rear Bumper Reinforcement <i>Net</i>		\$580.00	+
22	1	Rear End Panel <i>Deletd</i>		\$390.60	✓
23	1	Rear End Panel Top Garnish <i>Deletd</i>		\$90.80	✓

2695.50

2156.40

Subtotal:- \$6,237.00

Labour charges

To remove & refit cushion & trim board

~~\$280.00~~ 60

To remove & refit reverse sensor

~~\$100.00~~ 50

To remove & refit reverse camera

~~\$180.00~~ 50

To check wiring

~~\$100.00~~ 30

Tuff kote

~~\$150.00~~ 60

Towing fee

1750

\$150.00 +

Panel beating

~~\$1,000.00~~ 800

Spray painting

~~\$800.00~~ 700

Subtotal:- \$2,760.00

Total:- \$8,997.00

Adrian Lj

U/S 30/06/20.

05 hrs.

Supplementary: 237.68

total: 4144.08

U/S: 3.3K.

3.3K

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and**
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883
Email: SM_AUTOMOTIVE@HOTMAIL.COM
Tel: (65) 6747 9241 Fax: (65) 6741 7276
RCB No.: 53231488C

30/06/2020

Blk 1 Kaki Bukit Ave 6
01-43
Singapore 417883

Accident date: 23/06/2020

Supplementary repair cost for vehicle no: SMH8860K HONDA FIT HYBRID 1.5 19'

CHASSIS: GP51330682

S/n	Qty	Items	U/price	Amount
1	1	Rear Lock Sensor <i>called</i>		\$125.30 ✓ 38.10
2	1	Rear L/H Bumper Sponge <i>called</i>		\$89.00 ✓
3	1	Rear End Panel Top Garnish <i>Repeated</i>		\$185.00 X
4	1	Rear Windscreen PHV sticker <i>Not rec</i>		\$50.00 X

147.10

117.68

Subtotal :- \$449.30

Labour charges

To remove & refit rear windscreen

120

\$120.00 ✓

Subtotal :- \$120.00

Total:- \$569.30

Supplementary: 237.68