



CARRIAGE

199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address

Chan Soon Thien

316A Ang Mo Kio St 31

#23-307

Singapore 562316

Contact No Mobile: 92770118

Owner Name & Vehicle Info

Cust No/Name /Chan Soon Thien

Reg No/Reg Date SJW3422G / 18/03/201

Date In/Mileage / 0

Chassis No KNAFW411MA5191998

Engine No G4FC9H356242

Make/Model KIA/CERATO FORTE 1.6 A SX (2010)

Colour/Trim UD Clear White / WK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00081	Cash	29/06/2020/ 11:10	TLC	442 / CocoLu	16513			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								1925 2200.00
RENEW WINDMIRROR LH, FRT DOOR LH, REPAIR FRT BUMPER, FRT FENDER LH								
SIDE SILL LH, REAR DOOR LH, REAR FENDER LH, REAR BUMPER								120 200.00
E PNT88000								2520 3780.00
REMOVE & INSTALL DOOR TRIMS AND GLASS								
E PNT98000								80 90.00
SPRAY PAINT FOR FRT BUMPER, FRT FENDER LH, FRT DOOR LH, REAR DOOR LH								
REAR FENDER LH, REAR BUMPER, SIDE SILL LH, WINDMIRROR LH								
M SUNDRY								120.00
TRANSFER FRT AND REAR RIM								
B WHEELALIGNMENT								30.00
To Conduct Computerize Full Wheel Alignment								
A 90000001								200.00
CHECK WIRING & ELECTRICAL SYSTEM								
A 10028901								40.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								
USING HI-SCAN PRO TEST								
M SUNDRY								20.00
APPLY SEALANT FOR ACCIDENT PORTION								
M SUNDRY								14 27.00
Sundry								
M SUNDRY								Xm? 460.00
FRT DOOR TAPE LH -- ks863631M000								
M SUNDRY								
MODULE PNL & REG ASSY FRT DOOR LH -- 824011M010								
M PANEL ASSY-FRONT DOOR, LH					1.00	1132.00	00.00	1132.00
M BLACK TAPE-FRT DOOR FRAME UPR, ne					1.00	14.00	00.00	14.00
M MIRROR ASSY-OUTSIDE RR VIEW, LH					1.00	500.00	00.00	500.00
M WHEEL ASSY-ALUMINIUM FRT LH					1.00	728.00	00.00	728.00
M WHEEL ASSY-ALUMINIUM REAR LH					1.00	728.00	00.00	728.00
M WHEEL ASSY-ALUMINIUM FRT RH					1.00	728.00	00.00	728.00
M LATCH & ACTUATOR ASSY-FRT DR, L					1.00	213.00	00.00	213.00
SURVEYOR NAME: Rasul - Hp 90010068								
Confirm & accepted by					SURVEYOR SIGNATURE: [Signature]			
DATE: 29/06/2020 @ 1220					7% GST on			
REMARKS: 7 days					Total Payable			
Authorized signatory and company stamp								
					Nett			11,210.00
								784.70
								11,994.70

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.