

COMFORTDELDRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHC1094L

22/06/20

MAKE :

MODEL HYU- I40

CHIANG/CHINA

QTY	Parts Description/ Labour	TYPE	Unit Price	Amount
1	REAR BUMPER COVER			\$1,106.00
2	REAR BUMPER BRACKET SIDE LH/RH		\$35.60	\$71.20
10	REAR BUMPER CLIPS		\$2.20	\$22.00
1	REAR BUMPER REINFORCEMENT			\$428.40
1	REAR BUMPER UNDER COVER			\$228.00
1	REAR BUMPER REINFORCEMENT STAY		\$80.30	\$160.60
	SUB TOTAL			\$2,016.20
	20.00%			\$403.24
	DISCOUNTED TOTAL			\$1,612.96
1	REVERSE SENSOR			\$135.70
1	REAR BUMPER MAT			\$50.00
				\$185.70
	Labour Charge			
	Panel Beating			\$480.00
	Spray Painting Charge			\$280.00
	Remove/refix reverse sensor			\$60.00
	Tuff Kote			\$60.00
	Check Lighting			\$60.00
	TOTAL LABOUR			\$940.00
	ESTIMATE TOTAL			\$2,738.66
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Tanphk 97445749
 WP 23/6/20 3:15pm
 leaving after repair
 2 days
 tanphk@lkhauto.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

COMFORTDELGRO ENGINEERING

A member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd

205 Bras Basah Road Singapore 579701
Mainline - 65 6363 6280 Facsimile - 65 6280 9155

Workshops

33 Looiat Drive Singapore 508909 24 Serangoon Road Singapore 159156
383 Sin Ming Drive Singapore 575717 17 Sungei Kadut Way Singapore 158191
45 Pandan Road Singapore 109086 501 Pasir Ris Industrial Park A Singapore 166733

Date/Time: 22.06.2020 16:11

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order:

JC NO. 305406572

STOMER
MS COMFORT TRANSPORTATION PTE LTD
STOMER NO. 7010045
DRESS 383 SIN MING DRIVE
Singapore SINGAPORE 575717
(R) 65508755 (O)


COUNT CARD NO.

REGN NO.	SHC1094L	MILEAGE
MAKE	HYUNDAI	FUEL E.....1/2.....F
MODEL	I-40	DATE/TIME IN 22.06.2020 14:30
YR OF MANU.	25.08.2016	TARGET DATE
CHASSIS CODE	KMHLB41UMGU093350	COMPLETION DATE/TIME:

Accident Date: 22.06.2020
NATURE: 3P 22.06.2020

JOB DESCRIPTION

S/NO LABOR CODE DESCRIPTION



CKED & PASSED OUT BY

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

wedgement Slip

Exit Pass

No. SHC1094L CHIANG

Vehicle No. SHC1094L

Signature/Date

Signature/Date

Name of Service Advisor

Date

returned to Service Reception upon collection

To be kept by Security Guard