

JMFORTELDRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHC1094L

22/06/20

MAKE :

MODEL HYU- I40

CHIANG/CHINA

Qty	Parts Description/ Labour	TYPE	Unit Price	Amount
1	REAR BUMPER COVER			\$1,106.00
2	REAR BUMPER BRACKET SIDE LH/RH		\$35.60	\$71.20
10	REAR BUMPER CLIPS		\$2.20	\$22.00
1	REAR BUMPER REINFORCEMENT			\$428.40
1	REAR BUMPER UNDER COVER			\$228.00
1	REAR BUMPER REINFORCEMENT STAY		\$80.30	\$160.60
SUB TOTAL				\$2,016.20
20.00%				\$403.24
DISCOUNTED TOTAL				\$1,612.96
1	REVERSE SENSOR			\$135.70
1	REAR BUMPER MAT			\$50.00
				\$185.70
Labour Charge				
Panel Beating				\$480.00
Spray Painting Charge				\$280.00
Remove/refix reverse sensor				\$60.00
Tuff Kote				\$60.00
Check Lighting				\$60.00
TOTAL LABOUR				\$940.00
ESTIMATE TOTAL				\$2,738.66
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Tan Jiah 97445749
WP 23/6/20 3:15pm
Leaving after repair
2 days
tanjiah@lkhauto.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: