

Not Authorised
 2/5 \$3000
 4 days

make recall

VEHICLE NO SKE 4073G HYUNDAI ELANTRA

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(\$\$)	SURVEYOR'S ADJUSTMENT
	<u>PARTS (LIST ITEMS)</u>			
1	Rear bumper	495.40	7.1 124.60	✓
2	Rear bumper side retainer @\$75	65.00	0/5 bent 150.00	✓
1	Rear bumper reinforcement	415.00	one 578.00	✓
6	Rear bumper reinforcement brackets @45.20		11 271.20	X
1	Rear bumper inner foam		11 142.00	X
2	Rear bumper reflectors @\$78.50	68.50	0/5 scr 157.00	1/2 C
2	Rear bumper brackets @ \$98.20		11 196.40	X
1	Rear end panel	453.80	11 689.00	✓
1	Rear end panel top garnish		11 276.50	X
1	Rear spare tyre panel	REPAIR	11 0.00	X
1	RHS Rear fender		2 752.00	X
1	RHS Rear fender inner trim		11 298.60	X
1	RHS Rear fender inner shield		11 198.00	X
1	Rear windscreen moulding		11 67.30	X
1	Bootlid		11 1245.00	X
2	Bootlid hinge	REFIX	11 0.00	X
1	Boot edge weatherstrip		11 172.00	X
1	Bootlid logo (centre badge)		11 48.00	✓
1	Bootlid "ELANTRA" emblem	48.00	11 78.00	✓
1	Bootlid "HYUNDAI" emblem	52.00	11 98.00	✓
4	Bootlid rubber stopper @12.00		11 48.00	X
1	Bootlid lock		11 228.40	X
1	Bootlid lock catch		11 75.20	X
1	Bootlid inner trim	REFIX	11 0.00	X
1	Bootlid reflector RHS		11 346.20	X
1	Bootlid keyless lock actuator		11 242.50	X
1	RHS Taillamp	385.00	one 652.50	✓
			8134.40	
		less 20%	1626.88	20%
			6507.52	50%
	<u>SPECIAL NETT ITEMS</u>			
1set	Rear Bumper clips		11 80.00	50
1	Reverse sensor		11 280.00	X
1	Rear number plate w/base		11 75.00	X
1set	RHS Rear fender inner trim clips		11 60.00	X
1set	RHS Rear fender inner shield clips		11 60.00	X
1set	Bootlid inner trim clips		11 60.00	X
1	Rear windscreen sealant		11 100.00	X
1	Rear end panel sealant		11 100.00	50
1	Rear spare tyre panel insulator		11 120.00	X
	TOTAL PARTS		7442.52	

2030.7

VEHICLE NO SKE 4073G HYUNDAI ELANTRA

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR'S ADJUSTMENT
	<u>LABOUR</u>		
1	To remove the affected parts & components to commence repairs; panel beat & reshape the affected areas; replace damaged parts	1400.00	800
2	To supply paint materials, expandable items & putty, respray paint on parts replaced and repaired areas	1000.00	900
3	To remove, check and refix wiring at rear damaged areas	100.00	30
4	To remove and refix/replace inner trims, garnish and rear fittings etc. so as to facilitate repairs	250.00	80
5	To remove and refix rear bootlid components	100.00	X
6	To remove and replace reverse sensors and check for proper function	100.00	50
7	To remove and refix rear windscreen	140.00	X
8	To perform anti-rust treatment on affected areas	180.00	30
	Labour Total :	3270.00	
	TOTAL (PARTS & LABOUR):	10712.52	

NOTE: The parts listed in this preliminary estimate will be checked for damage after the vehicle is disassembled (dismantle). Additional damaged parts (if any) will be submitted as supplementary parts

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 2030.7
S02
P- 1015.35
S.N- 100.00
L- 1890.00
3005.35