



**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 9628P****AAD2006-057***Not Authorised**Resurvey B4 paint*

Vehicle No.:  
 Chassis No.:  
 Vehicle Make:  
 Vehicle Model:  
 Date of Accident :  
 Third Party Insurer :  
 Date of Registration :

**24 JUN 2020****SHD 9628P**

JTDKB3FU203082066

TOYOTA

PRIUS

21.6.2020

**AIG**

27/6/2019

<b>PART</b>		<b>LIST</b>	
1 MOULDING ASSY, BODY ROCKER PANEL, LH	\$	<i>n</i> 594.80	<i>x</i>
1 PANEL SUB-ASSY, QUARTER, LH	\$	<i>n</i> <del>871.50</del>	<i>x</i>
1 REAR FENDER LINER	\$	<i>sn</i> 139.80	} <i>x</i>
1 DUCT ASSY, QUARTER VENT, LH	\$	<i>sn</i> 67.00	
1 SEAL, REAR BUMPER SIDE, LH	\$	<i>sn</i> 88.50	
1 REAR BUMPER	\$	<i>sn</i> 442.60	
1 REAR BUMPER UNDER COVER (BLACK)	\$	<i>sn</i> 576.30	
1 REAR BUMPER SIDE RETAINER LH	\$	<i>sn</i> 116.50	} <i>x</i>
1 TAILLAMP LOWER LH	\$	<i>sn</i> 502.00	
1 TAILLAMP UPPER LH	\$	<i>wt</i> 451.80	<i>✓</i>
1 REAR BUMPER SIDE LH	\$	<i>sn</i> 123.70	<i>x</i>
1 PANEL SUB-ASSY, REAR DOOR, LH	\$	<i>sn</i> 1,294.90	<i>✓</i>
1 HANDLE ASSY, REAR DOOR OUTSIDE, LH	\$	<i>sn</i> 97.40	<i>x</i>
1 TAPE, BLACK OUT, NO.1 LH	\$	<i>na</i> 21.90	<i>—</i>
1 TAPE, BLACK OUT, NO.2 LH	\$	<i>na</i> 34.90	<i>—</i>
1 TAPE, BLACK OUT, NO.3 LH	\$	<i>na</i> 15.40	<i>—</i>
1 WEATHERSTRIP, REAR DOOR, LH	\$	<i>sn</i> 180.10	<i>x</i>
1 LOCK ASSY, REAR DOOR W/ MOTOR, LH	\$	<i>n</i> 561.90	<i>x</i>
1 REAR WHEEL RIM	\$	<i>sn</i> 1,879.40	<i>x</i>
1 REAR WHEEL RIM COVER	\$	<i>sn</i> 211.50	<i>x</i>
<b>TOTAL</b>	<b>\$</b>	<b>8,271.90</b>	
<b>25%</b>	<b>\$</b>	<b>2,067.98</b>	
	<b>\$</b>	<b>6,203.93</b>	

**Special Nett**

1 REAR DOOR STICKER '6555-3333'	\$	<i>na</i> 100.00	<i>born</i>
1SET REAR BUMPER CLIP	\$	<i>na</i> 75.00	<i>x</i>
2 REAR WINDSCREEN SEALANT	\$	<i>na</i> 140.00	<i>x</i>
1 WINDSCREEN MOULDING	\$	<i>na</i> 180.00	<i>x</i>

**Trans-cab Auto Services Pte Ltd**

AAD2006-057

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 9628P**

1 REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>na</i>	120.00	}	<i>X</i>
1SET REAR FENDER LINER CLIP	\$	<i>na</i>	40.00		
1 REAR TYRE 195/65/15	\$	<i>na</i>	350.00		
1SET REAR BUMPER RETAINER CLIP	\$	<i>na</i>	40.00		
1SET ROCKER PANEL MOULDING CLIP	\$	<i>na</i>	45.00		
1SET TAILLAMP LOWER CLIP	\$	<i>na</i>	35.00		
1SET TAILLAMP UPPER CLIP	\$	<i>na</i>	35.00		
1 REAR BUMPER PROTECTOR	\$	<i>na</i>	120.00		
<b>TOTAL</b>	<b>\$</b>		<b>1,280.00</b>		

<b>TOTAL PARTS</b>	<b>\$</b>		<b>7,483.93</b>
--------------------	-----------	--	-----------------

**LABOUR**

To transfer of Rear Fender fittings, attachments and perform water seepage test.	\$		170.00	}	<i>601</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$		380.00		
To check steering geometry and computer wheel alignment	\$	<i>na</i>	220.00		<i>X</i>
To transfer of Rear Bumper fittings, attachments and perform water seepage test.	\$	<i>na</i>	170.00		<i>X</i>
To transfer of rear big windscreen glass to facilitate bodywork repair.	\$	<i>na</i>	170.00		<i>X</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		6,000.00		<i>4001</i>
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>m</i>	380.00		<i>X</i>
To transfer of door fittings, attachment and perform water seepage test.	\$		170.00		<i>601</i>

**Trans-cab Auto Services Pte Ltd**

**AAD2006-057**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 9628P**

To reinstall rear bumper parking sensor.	\$	<i>nn</i>	170.00	X
To transfer of rear small windscreen glass to facilitate bodywork repair.	\$	<i>nn</i>	170.00	X
Putty And Spray Painting Of The Affected Portion.	\$		6,000.00	<i>6601</i>
To Check Electrical Lighting Concerned.	\$		170.00	<i>201</i>
To Rust-Proofing Of The Affected Areas.	\$		170.00	<i>301</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i>	170.00	X
<b>TOTAL</b>	<b>\$</b>		<b>14,510.00</b>	
<b>Over All Total</b>	<b>\$</b>		<b>21,993.93</b>	

**(PART-BY-PART) Repair Days**

*20 DAYS*  
*3 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

> [Back to OneMotoring](#)

### Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	878K
<b>Vehicle Details</b>	
Vehicle No.:	SHD9628P
Vehicle to be Exported:	Yes
Intended Deregistration Date:	22 Jun 2020
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS 5DR HATCHBACK (AUTO)
Primary Colour:	Red
Manufacturing Year:	2018
Engine No.:	2ZR2C34919
Chassis No.:	JTDKB3FU203082066
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$26,605.00
Original Registration Date:	27 Jun 2019
First Registration Date:	27 Jun 2019
Transfer Count:	0
Actual ARF Paid:	\$14,247.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Jun 2027
PARF Rebate Amount:	\$10,685.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	26 Jun 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$23,872.00
COE Rebate Amount:	\$19,097.00
<b>Total Rebate Amount:</b>	<b>\$29,782.00</b>
<b>Message</b>	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 22 Jun 2020

OK