

**Trans-cab Auto Services Pte Ltd**  
 No. 2 Ang Mo Kio Street 63 Singapore 569111  
 Tel No. : 6287 6666 Fax No. : 6257 1330  
 CO./GST Reg. No. 201019626G  
**SHD 9628P**

AAD2006-057

*Not Authorised*  
*Resurvey B4 paint*

Vehicle No.:  
 Chassis No.:  
 Vehicle Make: **24 JUN 2020**  
 Vehicle Model:  
 Date of Accident :  
 Third Party Insurer :  
 Date of Registration :

**SHD 9628P**  
 JTDKB3FU203082066  
 TOYOTA  
 PRIUS  
 21.6.2020  
**AIG**  
 27/6/2019

- PART**
- 1 MOULDING ASSY, BODY ROCKER PANEL, LH
  - 1 PANEL SUB-ASSY, QUARTER, LH
  - 1 REAR FENDER LINER
  - 1 DUCT ASSY, QUARTER VENT, LH
  - 1 SEAL, REAR BUMPER SIDE, LH
  - 1 REAR BUMPER
  - 1 REAR BUMPER UNDER COVER (BLACK)
  - 1 REAR BUMPER SIDE RETAINER LH
  - 1 TAILLAMP LOWER LH
  - 1 TAILLAMP UPPER LH
  - 1 REAR BUMPER SIDE LH
  - 1 PANEL SUB-ASSY, REAR DOOR, LH
  - 1 HANDLE ASSY, REAR DOOR OUTSIDE, LH
  - 1 TAPE, BLACK OUT, NO.1 LH
  - 1 TAPE, BLACK OUT, NO.2 LH
  - 1 TAPE, BLACK OUT, NO.3 LH
  - 1 WEATHERSTRIP, REAR DOOR, LH
  - 1 LOCK ASSY, REAR DOOR W/ MOTOR, LH
  - 1 REAR WHEEL RIM
  - 1 REAR WHEEL RIM COVER

	<b>LIST</b>		
\$	<i>R</i>	594.80	<i>X</i>
\$	<i>R B</i>	871.50	<i>X</i>
\$	<i>SL</i>	139.80	} <i>X</i>
\$	<i>SL</i>	67.00	
\$	<i>SL</i>	88.50	
\$	<i>SL</i>	442.60	
\$	<i>SL</i>	576.30	
\$	<i>SL</i>	116.50	
\$	<i>SL</i>	502.00	} <i>X</i>
\$	<i>WT</i>	451.80	
\$	<i>SL</i>	123.70	<i>X</i>
\$	<i>B4</i>	1,294.90	<i>✓</i>
\$	<i>SL</i>	97.40	<i>X</i>
\$	<i>RE</i>	21.90	<i>—</i>
\$	<i>RE</i>	34.90	<i>—</i>
\$	<i>RE</i>	15.40	<i>—</i>
\$	<i>SL</i>	180.10	<i>X</i>
\$	<i>R</i>	561.90	<i>X</i>
\$	<i>SL</i>	1,879.40	<i>X</i>
\$	<i>SL</i>	211.50	<i>X</i>

<b>TOTAL</b>	\$	<b>8,271.90</b>
<b>25%</b>	\$	<b>2,067.98</b>
	\$	<b>6,203.93</b>

**Special Nett**

1 REAR DOOR STICKER '6555-3333'	\$	<i>RE</i> 100.00	<i>6052</i>
1SET REAR BUMPER CLIP	\$	<i>RE</i> 75.00	<i>X</i>
2 REAR WINDSCREEN SEALANT	\$	<i>RE</i> 140.00	<i>X</i>
1 WINDSCREEN MOULDING	\$	<i>RE</i> 180.00	<i>X</i>

*50259*  
*15/6/20*  
*138519*

**Trans-cab Auto Services Pte Ltd**

AAD2006-057

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 9628P**

1 REAR WINDSCREEN INNER SPONGE SEAL	\$	<i>na</i>	120.00	} X
1SET REAR FENDER LINER CLIP	\$	<i>na</i>	40.00	
1 REAR TYRE 195/65/15	\$	<i>sn</i>	350.00	
1SET REAR BUMPER RETAINER CLIP	\$	<i>na</i>	40.00	
1SET ROCKER PANEL MOULDING CLIP	\$	<i>na</i>	45.00	
1SET TAILLAMP LOWER CLIP	\$	<i>na</i>	35.00	
1SET TAILLAMP UPPER CLIP	\$	<i>na</i>	35.00	
1 REAR BUMPER PROTECTOR	\$	<i>na</i>	120.00	
<b>TOTAL</b>	<b>\$</b>		<b>1,280.00</b>	

**TOTAL PARTS \$ 7,483.93**

**LABOUR**

To transfer of Rear Fender fittings, attachments and perform water seepage test.	\$		170.00	} 601
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$		380.00	
To check steering geometry and computer wheel alignment	\$	<i>na</i>	220.00	X
To transfer of Rear Bumper fittings, attachments and perform water seepage test.	\$	<i>h</i>	170.00	X
To transfer of rear big windscreen glass to facilitate bodywork repair.	\$	<i>h</i>	170.00	X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		6,000.00	400
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	<i>na</i>	380.00	X
To transfer of door fittings, attachment and perform water seepage test.	\$		170.00	601

**Trans-cab Auto Services Pte Ltd**

AAD2006-057

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHD 9628P**

To reinstall rear bumper parking sensor.	\$	<i>nn</i>	170.00	X
To transfer of rear small windscreen glass to facilitate bodywork repair.	\$	<i>nn</i>	170.00	X
Putty And Spray Painting Of The Affected Portion.	\$		6,000.00	<i>6601</i>
To Check Electrical Lighting Concerned.	\$		170.00	<i>201</i>
To Rust-Proofing Of The Affected Areas.	\$		170.00	<i>301</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i>	170.00	X
<b>TOTAL</b>	<b>\$</b>		<b>14,510.00</b>	
<b>Over All Total</b>	<b>\$</b>		<b>21,993.93</b>	

**(PART-BY-PART) Repair Days**

*20 DAYS*

*3 days*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: