

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20006691/UGA3Q2

Date: 13/08/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : FBM9732U	Insured Vehicle No :	SHB6232C
Date of Loss: 22/06/2020	Nature of Claim: TP	Claim No: MCT20060235

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	FBM9732U		
Make & Model:	YAMAHA YBR125, 124cc (M)	Engine No:	E3F5E044884
Reg. Date:	30/05/2018 (Man. Year: 2017)	Chassis No:	LBPRI101000059662
Colour:	Red	Odometer:	75582 km
Engine Capacity:	124 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	2.75-18	Rear Tyre Size:	90/90-18
Front Left Side:	Metzeler 7 mm	Rear Left Side:	Metzeler 7 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,211.00	1,482.60	1,728.40	53.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	308.00	255.00	53.00	17.21
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	3,519.00	1,737.60	1,781.40	50.62
+ GST 7.00/7.00% (\$\$)	246.33	121.63	124.70	50.62
Nett Amount (\$\$)	3,765.33	1,859.23	1,906.10	50.62
+ Loss of Use (2.0 x S\$30.00/day) (\$\$)		60.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		1,926.68		

INSPECTION

Date of Assignment:	25/06/2020	
Date Inspected:	26/06/2020	Inspected At:
		Ban Hock Hin Co. Pte Ltd (HQ)
		No. 6 Defu Lane 4
		Singapore 539410
Estimated Period of Repair:	3.0 days	

Adjuster: MARCUS CHUA

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 29 Jul 2020)	
Parts:	N/A	YAMAHA YBR125 124cc (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBM9732U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*ALIGNMENT BODY/FRAME	Not Necessary	126.00 F	*- FL
2	1		*BRACKET FOOTREST RH (50%)	Bent	117.00 FS	*58.50 FS
3	1		*COVER TAIL CENTER	Cracked	118.00 F	*118.00 FL
4	1		*COVER TAIL LH (RED)	Cracked	77.00 F	*77.00 FL
5	1		*COVER TAIL RH (RED)	Cracked	90.00 F	*90.00 FL
6	1		*COVER TANK SIDE RH (RED)	Repair	119.00 F	*- FL
7	1		*CRASH BAR	Bent	203.00 F	*203.00 FL
8	1		*FOOTREST FRONT	Torn	54.00 F	*54.00 FL
9	1		*GASKET EXHAUST PIPE	Necessary	6.00 F	*6.00 FL
10	1		*LAMP SIGNAL REAR RH	Cracked	16.00 F	*16.00 FL
11	1		*LEVER BRAKE	Scratched	19.00 F	*19.00 FL
12	1		*MIRROR RH	Cut	35.00 F	*35.00 FL
13	1		*MUDGUARD REAR	Cut	68.00 F	*68.00 FL
14	1		*PIPE EXHAUST ASSY (50%) (\$1500.00)	Dented / Bent	2,100.00 FS	*750.00 FS
15	1		*RUBBER FOOTREST FRONT	Torn	14.00 F	*14.00 FL
16	1		*STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT	Necessary	19.00 F	*19.00 FL
17	1		*VISOR	Scratched	30.00 F	*30.00 FL
					Sub Total (\$\$)	3,211.00 1,557.50
					- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00 74.90
					Total Parts (\$\$)	3,211.00 1,482.60

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TRANSPORT CHARGES	New	56.00	35.00
2	LABOUR -LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS	New	252.00	220.00
Gross Labour Cost (\$\$)			308.00	255.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >