



Yong Chin Chern Motor Works

38 Woodland Industrial Park E1 Singapore 757700

Tel: 6565 2492 Fax: 6314 4819

Email: sales@yccmotors.com Website: www.yccmotors.com

CSN^{NI}: 32153700M-PTE-01

Our reference: YCCE0010
 Attn: Budget Direct Motor Claim Dept
 LKK

Date: 27th June 2020
 Vehicle no: SKR 7221 H
 Make/Model: Toyota Altis 1.6 CVT
 Chassis/Engine: MR053REH104527086
 Claim Ref: LCH.lg/W11Y2C-10249.20

Accident Date: 23th June 2020

List Item	Quantity	Unit Price	Amount(S\$)
1. REAR BOOT / PP	1PC		785.24 /
2. REAR BOOT HINGE BT	2PCS	169.07	338.14 220
3. REAR BOOT LOCK / Jam	1PC		375.48 /
4. REAR BOOT WEATHER STRIP / CR4	1PC		148.60 /
5. REAR BUMPER / CR4	1PC		689.68 /
6. REAR UPPER L/R RETAINER X Svc	2PCS	86.24	172.48 X
7. REAR BUMPER CENTER PAD / NEC	1PC		3.00 /
8. REAR BUMPER L/R FENDER RETAINER X Svc	2PCS	140.31	280.62 X
9. REAR BUMPER L/R SEAL X nec	2PCS	98.03	196.06 X
10. REAR BUMPER REINFORCEMENT / BT	1PC		396.97 /
11. REAR L/R BUMPER REINFORCEMENT ARM X Svc	2PCS	89.74	179.48 X
12. REAR END PANEL MOULDING / CR4	1PC		295.36 /
13. REAR BOOT GARNISH X Svc	1PC		278.90 X
14. REAR END PANEL BT X R	1PC		721.60 X
15. REAR SPARE TYRE PANEL X Svc	1PC		807.90 X
16. REAR L/R FLOOR SIDE PANEL X Svc	1PC	186.43	372.86 X
17. BOOT "TOYOTA" EMBLEM X / NEC	1SET		70.86 /
18. BOOT "ALTIS" EMBLEM / NR	1SET		107.76 73.84
19. BOOT "TOYOTA LOGO" EMBLEM / NEC	1SET		75.41 /
20. BOOT TAILLAMP LEFT X Svc	1PC		327.64 X
21. BOOT TAILLAMP RIGHT / SCR	1PC		327.64 /
22. FENDER TAILLAMP LEFT X Svc	1PC		358.90 X
23. FENDER TAILLAMP RIGHT / CRA	1PC		358.90 /

List Total
 Trade Discount 25.00%

3,820.98
 - 25%
 2,865.74

SPECIAL NETT ITEMS

1. REVERSE SENSOR / short	1SET		386.72 /
2. BUMPER CLIP / NEC	20PCS	1.30	26.00 /
3. BOOT CLIP / NEC	10PCS	1.30	13.00 /
4. SILICONE SEALANT / NEC	1TUBS	30.00	30.00 /

Sub-total cost for parts

455.72 455.72





Yong Chin Chern Motor Works

38 Woodland Industrial Park E1 Singapore 757700

Tel: 6565 2492 Fax: 6314 4819

Email: sales@yccmotors.com Website: www.yccmotors.com

CSN^{NI}: 32153700M-PTE-01

LABOR

1. TO DISMANTLE & REPLACE DAMAGED PARTS/PANEL BEATING
2. TO APPLY RUST PROOFING ON ADJACENT PANELS
3. TO PUTTY AND SPRAY PAINT ON AFFECTED AREAS
4. TO REMOVE AND RENEW BUMPER SENSOR(S) WITH CHECK

600.00 ✓
 100.00 50
 800.00 750
 100.00 30

 1600.00 1,430

Labor Total

Total Estimate Cost S\$:

7807.83

Repair day - 4 days

L/S
After paint photo

P = 2,865.74
 N = 455.72
 L = 1,430

 4,751.46
 - 2090


 3,801.17

L/S
\$ 3,800
4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:



Yong Chin Chern Motor Works

