

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20006710/R1GS3Q2

Date: 03/11/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No: D20MCV0001695
Claimant Vehicle No : SML4123K	Insured Vehicle No : GBJ4209M
Date of Loss: 25/06/2020	Nature of Claim: TP
	Claim No: MCV2020D0001188

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SML4123K		
Make & Model:	SUBARU FORESTER, 2.0 I-L EYESIGHT AWD CVT (A)	Engine No:	FB20YG03466
Reg. Date:	21/05/2019 (Man. Year: 2018)	Chassis No:	JF1SK7KL5KG010250
Colour:	Brown	Odometer:	14008 km
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/60 R17	Rear Tyre Size:	225/60 R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	707.17	508.45	198.72	28.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,780.00	2,080.00	1,700.00	44.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,487.17	2,588.45	1,898.72	42.31
+ GST 7.00/7.00% (S\$)	314.10	181.19	132.91	42.31
Nett Amount (S\$)	4,801.27	2,769.64	2,031.63	42.31
+ Car Rental (4.0 x S\$110.00/day + 7.00% GST) (S\$)		470.80		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,242.44		

INSPECTION

Date of Assignment:	26/06/2020	
Date Inspected:	29/06/2020 Inspected At:	Motor Image Enterprises Pte Ltd (Leng Kee) 25 Leng Kee Road Singapore 159097
Estimated Period of Repair:	4.0 days	

Adjuster: MOHD RASUL

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 17 Sep 2020)
Parts: M1-SUV	SUBARU FORESTER 2.0 I-L EYESIGHT AWD CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SML4123K)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*GARNISH AY DR R ULH -UPPER	Deformed	108.00 FN	*108.00 FN
2	1		*BUMPER FACE R STD	Deformed	482.40 FN	*482.40 FN
3	1		*BRKT SD R RH	Serviceable	14.40 FN	*- FN
4	1		*BRKT SD R LH	Necessary	14.40 FN	*14.40 FN
5	1		*CLIP	Necessary	5.76 FN	*5.76 FN
6	1		*GARNISH AY R QTR LH	Serviceable	99.00 FN	*- FN
7	1		*SUNDRIES	Necessary	100.00 FS	*20.00 FS
8	1		*BALANCE TYRE (REAR LHS)	Not Necessary	28.00 FS	*- FS

F=Franchise part. S=SpcNett. N=NettItemDisc.

Sub Total (S\$)	851.96	630.56
- Nett Item Discount on N Items 20.00/20.00% (S\$)	144.79	122.11
Total Parts (S\$)	707.17	508.45

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	T OCONDUCT 4-WHEEL ALIGNMENT	New	200.00	0.00
2	TO CONDUCT PANEL BEATING REAR QUARTER PANEL LHS	New	560.00	560.00
3	TO REPLACE REAR BUMPER ,BRKT RHS & BRKT LHS	New	1,680.00	560.00
4	TO REPSRAY REAR QUARTER PANEL AND REAR BUMPER	New	1,260.00	880.00
5	TO REMOVE AND REINSTALL REVERSE SENSOR	New	80.00	80.00
			Gross Labour Cost (\$\$)	2,080.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >