

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
18 SIN MING LANE #01-08 MIDVIEW CITY
SINGAPORE 573960

Contact : 66550005-GRAB 97555507

ESTIMATE

TP Chinn.

Repair Code : CLM16290

Date in : 23/06/2020

Jvonne

Vehicle Num. : SLQ6124E

Model : HONDA VEZEL 1.5X HYBRID AT ABS D/AIRBAG 2WD

Chassis/Eng# : RU31248678/LEB5948696

Parts and Labour Assessment

Description of part	Qty	Unit Price	Amount
REAR BUMPER Distorted	1	762.70	✓ 762.70
REAR BUMPER LOWER COVER Not new	1	250.00	X 250.00
REAR BUMPER REFLECTOR L/R Cracked	2	141.10	✓ 282.20
REAR BUMPER SIDE L/R Repair	2	195.00	X 390.00
REAR BUMPER SIDE RETAINER L/R New	2	23.00	✓ 46.00
REAR END PANEL Dented	1	415.60	✓ 415.60
REAR END PANEL BUZZLE SENSOR Cracked	1	85.20	✓ 85.20
REAR END PANEL INNER TOP GARNISH Deformed	1	98.00	✓ 98.00
REAR EXHAUST CHROME TAIL PIPE Not new	1	135.00	X 135.00
REAR FENDER ARCH GARNISH L/R Cracked	2	195.00	✓ 390.00
REAR FENDER INNER TRIM GARNISH L/R Cracked	2	295.00	✓ 590.00
REAR FLOOR PANEL COMPARTMENT TRAY GARNISH Cracked	1	485.30	✓ 485.30
REAR FLOOR PANEL TOP BOARD COVER Deformed	1	430.30	✓ 430.30
REAR NUMBER PLATE LAMP L/R Not new	2	25.80	X 51.60
REAR TAILGATE Distorted	1	953.50	✓ 953.50
REAR TAILGATE 'HYBRID' EMBLEM New	1	75.80	✓ 75.80
REAR TAILGATE 'VEZEL' EMBLEM	1	56.20	✓ 56.20
REAR TAILGATE DAMPER L/R Not new	2	180.00	X 360.00

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

GRAB RENTALS PTE LTD

18 SIN MING LANE #01-08 MIDVIEW CITY

SINGAPORE 573960

Contact : 66550005-GRAB 97555507

ESTIMATE

Repair Code : CLM16290

Date in : 23/06/2020

Vehicle Num. : SLQ6124E

Model : HONDA VEZEL 1.5X HYBRID AT ABS D/AIRBAG 2WD

Chassis/Eng# : RU31248678/LEB5948696

REAR TAILGATE INNER PULL GARNISH	<i>Not run</i>	1	27.50	X	27.50
REAR TAILGATE INNER TOP TRIM GARNISH	<i>Not run</i>	1	85.00	X	85.00
REAR TAILGATE INNER TRIM GARNISH	<i>could</i>	1	153.40	✓	153.40
REAR TAILGATE INNER TRIM GARNISH L/R	<i>could</i>	2	50.00	✓	100.00
REAR TAILGATE MECHANISM LOCK	<i>Damaged</i>	1	180.00	✓	180.00
REAR TAILGATE MECHANISM LOCK STRIKER	<i>Not run</i>	1	27.50	X	27.50
REAR TAILGATE OPENER SENSOR	<i>Not run</i>	1	175.50	X	175.50
REAR TAILGATE OUTER GARNISH	<i>could</i>	1	220.00	✓	220.00
REAR TAILGATE OUTER GARNISH 'H' LOGO EMBLEM	<i>run</i>	1	25.00	✓	25.00
REAR TAILGATE REFLECTOR BACK RUBBER GASKET L/R	<i>Not run</i>	2	38.50	✓	77.00
REAR TAILGATE REFLECTOR L/R	<i>Not</i>	2	413.20	✓	826.40
REAR TAILGATE REVERSE CAMERA	<i>Damaged</i>	1	1020.70	<i>550/SN</i>	1,020.70
REAR TAILGATE RUBBER GUIDE STOPPER L/R	<i>Not run</i>	2	18.50	X	37.00
REAR TAILGATE WEATHER STRIP	<i>Not</i>	1	96.80	✓	96.80
REAR TAILGATE WIPER ARM	<i>Not</i>	1	42.00	✓	42.00
REAR TAILGATE WIPER ARM BLADE	<i>Not</i>	1	18.00	✓	18.00
REAR TAILGATE WIPER ARM COVER	<i>Not</i>	1	25.00	✓	25.00
REAR TAILGATE WIPER MOTOR	<i>Damaged</i>	1	205.00	✓	205.00

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 Heavy Vehicle #01-08 Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

GRAB RENTALS PTE LTD

18 SIN MING LANE #01-08 MIDVIEW CITY

SINGAPORE 573960

Contact : 66550005-GRAB 97555507

ESTIMATE

Repair Code : CLM16290

Date in : 23/06/2020

Vehicle Num. : SLQ6124E

Model : HONDA VEZEL 1.5X HYBRID AT ABS D/AIRBAG 2WD

Chassis/Eng# : RU31248678/LEB5948696

REAR TAILGATEWINDSCREEN GLASS	Shattered	1	1350.10	✓	1,350.10
REAR TAILGATEWINDSCREEN INNER SEAL	} New	9138.70 2	50.00	✓	100.00
REAR TAILGATEWINDSCREEN MOULDING		7310.96 2	50.00	✓	100.00
REAR TAILLAMP L R	lt	SN 5502	474.60	✓	949.20
Subtotal before discount					11,698.50

Percentage discount 20%

2,339.70

Sub-total 1

9,358.80

REAR BUMPER CLIPS - SET	New	1	50.00	30	50.00
REAR BUMPER REVERSE SENSOR	Damaged	1	250.00	20	250.00
REAR FENDER ARCH GARNISH CLIPS L/R - SET	New	2	20.00	✓	40.00
REAR FENDER INNER TRIM GARNISH CLIPS L/R - SET	new	2	30.00	✓	60.00
REAR NUMBER PLATE	lt	1	25.00	✓	25.00
REAR NUMBER PLATE HOLDER	New	1	50.00	X	50.00
REAR TAILGATE INNER TRIM GARNISH CLIPS - SET	New	1	50.00	30	50.00
REAR TAILGATE OUTER GARNISH CLIPS - SET	new	1	40.00	20	40.00
REAR TAILGATE SPOILER CLIPS - SET	New	1	50.00	X	50.00
REAR TAILGATE WINDSCREEN SEALANT	new	1	60.00	✓	60.00
REAR TAILGATE WINDSCREEN SOLAR FILM	New	1	400.00	20	400.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
 18 SIN MING LANE #01-08 MIDVIEW CITY
 SINGAPORE 573960

Contact : 66550005-GRAB 97555507

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ESTIMATE

Repair Code : CLM16290
 Date in : 23/06/2020
 Vehicle Num. : SLQ6124E
 Model : HONDA VEZEL 1.5X HYBRID AT ABS D/AIRBAG 2WD
 Chassis/Eng# : RU31248678/LEB5948696

	Subtotal before discount	1,075.00
Percentage discount	0%	0.00
	Sub-total 2	1,075.00
	Parts-total	10,433.80

LABOUR

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.	✓	60.00
To remove, change windscreen.	120	150.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	80	120.00
To send vehicle for cleaning, shampoo, upholstery and cushion seat.	50	150.00
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	850	1,200.00
To remove and change exhaust silencer box with pipe, re-align where necessary consistent to the accident.	X	120.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	2220	900.00
To apply anti-rust chemical on repaired and replaced panel.	80	100.00
To transfer rear tailgate inner trim board, wiper motor, mechanism lock outer handle.	✓	80.00
	Labour Total	2,980.00
	Parts & Labour Total	13,413.80

Total: 10745.96
 L/S: 8.6K
 07 Days.
 8.6K