

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Status
Main	25 Jun 2020	25 Jun 2020 10:33 \$0.00	26 Jun 2020 10:49 Edit Adj Rpt	\$0.00 Edit Estimates	\$0.00 View Rpt	Pending for Survey Report

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	MOHAMMAD AZFAR BIN HASHIM, ID: S8415991C, Tel: +6597896047, Email: AZFAR.HASHIM@GMAIL.COM		
Vehicle Reg. No.:	SGM1623U	Date of Loss:	23/06/2020 08:00 - :59 [164 Months and 13 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD / SNM20D202242/C01/TANGHL2	Policy/Cover Note No.:	DMPCSN3076441900 (Comprehensive)
		Excess:	S\$1,500.00
Repairer:	Car City Auto Centre Pte Ltd (HQ) Blk 9006 #01-198, Tampines Street 93, 528840 Tampines - Tel: 6781 0300		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Ben Tang]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 07/07/2020]		
Driver/Custodian:	MOHAMMAD AZFAR BIN HASHIM (36 / Male) , NRIC: S8415991C, Tel: +6597896047 Email: AZFAR.HASHIM@GMAIL.COM		
Adj Asg. Remarks:	Excess \$1,500.00 applicable.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- CHINA_TAIPING (08/07/2020): **Alert - Adj Mandate Revoked - SGM1623U - Claim Handler: Ben Tang**

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

SGM1623U (SNM20D202242/C01/TANGHL2)

OD

Jun 23 2020 8:00AM

[MOHAMMAD AZFAR BIN HASHIM]

Car City Auto Centre Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Video			1 per page	☒
No	Finalized On	Car City Auto Centre Pte Ltd (HQ)		Thumbnail Print
1	24/06/20 14:39	Video - Accident [Linked Accident Report Documents]		Load MP4
Assessment Reports			1 per page	☒
No	Finalized On	Car City Auto Centre Pte Ltd (HQ)		Thumbnail Print
1	25/06/20 10:33	Repairer Estimates		Load HTM
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	29/06/20 09:20	Adjuster Immediate Advice		Load HTM
Photos/Images			3 per page	☒
No	Finalized On	Car City Auto Centre Pte Ltd (HQ)		Thumbnail Print
1	25/06/20 10:32	INSURED TYRE BRAND		Load JPG
2	25/06/20 10:32	INSURED TYRE SIZE		Load JPG
3	25/06/20 10:32	INSURED MILEAGE		Load JPG
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail Print
1	26/06/20 17:56	Odometer Reading		Load JPG
2	26/06/20 17:56	Chassis Number		Load JPG
3	26/06/20 17:57	General View		Load JPG
4	26/06/20 17:57	General View		Load JPG
5	26/06/20 17:57	General View		Load JPG
6	26/06/20 17:57	General View		Load JPG
7	26/06/20 17:57	General View		Load JPG
8	26/06/20 17:57	General View		Load JPG
9	26/06/20 17:57	General View		Load JPG
10	26/06/20 17:57	General View		Load JPG
11	26/06/20 17:57	General View		Load JPG
12	26/06/20 17:57	General View		Load JPG
13	26/06/20 17:57	General View		Load JPG
14	26/06/20 17:57	General View		Load JPG
15	26/06/20 17:57	General View		Load JPG
16	26/06/20 17:57	General View		Load JPG
17	26/06/20 17:57	General View		Load JPG
18	26/06/20 17:57	General View		Load JPG
19	26/06/20 17:57	General View		Load JPG
20	26/06/20 17:57	General View		Load JPG
21	26/06/20 17:57	General View		Load JPG
22	26/06/20 17:57	General View		Load JPG
23	26/06/20 17:57	General View		Load JPG
24	26/06/20 17:57	General View		Load JPG
25	26/06/20 17:57	General View		Load JPG
26	26/06/20 17:57	General View		Load JPG
27	26/06/20 17:57	General View		Load JPG
28	26/06/20 17:57	General View		Load JPG
29	26/06/20 17:57	General View		Load JPG

Video				1 per page	☒
No	Finalized On	Car City Auto Centre Pte Ltd (HQ)		Thumbnail	Print
30	26/06/20 17:57	General View		Load JPG	☒
31	26/06/20 17:57	General View		Load JPG	☒
32	26/06/20 17:57	General View		Load JPG	☒
33	26/06/20 17:57	General View		Load JPG	☒
34	26/06/20 17:57	General View		Load JPG	☒
35	26/06/20 17:57	General View		Load JPG	☒
36	26/06/20 17:57	General View		Load JPG	☒
37	26/06/20 17:57	General View		Load JPG	☒
38	26/06/20 17:57	General View		Load JPG	☒
39	26/06/20 17:57	General View		Load JPG	☒
40	26/06/20 17:57	General View		Load JPG	☒
41	26/06/20 17:57	General View		Load JPG	☒
42	26/06/20 17:57	General View		Load JPG	☒
43	26/06/20 17:57	General View		Load JPG	☒
44	26/06/20 17:57	General View		Load JPG	☒
45	26/06/20 17:57	General View		Load JPG	☒
46	26/06/20 17:57	General View		Load JPG	☒
47	26/06/20 17:57	General View		Load JPG	☒
48	26/06/20 17:57	General View		Load JPG	☒
49	26/06/20 17:57	General View		Load JPG	☒
50	26/06/20 17:57	General View		Load JPG	☒
51	26/06/20 17:57	General View		Load JPG	☒
52	26/06/20 17:57	General View		Load JPG	☒
53	26/06/20 17:57	General View		Load JPG	☒
54	26/06/20 17:57	General View		Load JPG	☒
55	26/06/20 17:57	General View		Load JPG	☒
56	26/06/20 17:57	General View		Load JPG	☒
57	26/06/20 17:57	General View		Load JPG	☒
Documentation				1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	14/07/20 08:57	LETTER		Load PDF	
2	14/07/20 08:57	LTA REBATE		Load PDF	

Linked Accident Report Documents

Video					View in Browser	☒
No	Finalized On	Car City Auto Centre Pte Ltd (HQ)		Thumbnail	Print	
1	24/06/20 14:39	Video - Accident		Load MP4		
Assessment Reports					1 per page	☒
No	Finalized On	Car City Auto Centre Pte Ltd (HQ)		Thumbnail	Print	
1	24/06/20 16:53	Accident Statement		Load HTM		
Photos/Images					3 per page	☒
No	Finalized On	Car City Auto Centre Pte Ltd (HQ)		Thumbnail	Print	
1	24/06/20 14:41	SCENE PHOTO		Load JPG	☒	
2	24/06/20 14:41	SCENE PHOTO		Load JPG	☒	
3	24/06/20 14:41	SCENE PHOTO		Load JPG	☒	
4	24/06/20 14:41	SCENE PHOTO		Load JPG	☒	
5	24/06/20 14:41	SCENE PHOTO		Load JPG	☒	
6	24/06/20 14:41	SCENE PHOTO		Load JPG	☒	
Documentation					1 per page	☒
No	Finalized On	Car City Auto Centre Pte Ltd (HQ)		Thumbnail	Print	

Video				1 per page	☒
No	Finalized On	Car City Auto Centre Pte Ltd (HQ)		Thumbnail	Print
1	24/06/20 14:37	Sketch Plan		Load TIF	
2	24/06/20 14:37	Sketch Plan #2		Load TIF	
3	24/06/20 14:38	INSURED CI		Load TIF	
4	24/06/20 14:48	POLICE REPORT PAGE 1		Load TIF	
5	24/06/20 14:48	POLICE REPORT PAGE 2		Load TIF	
6	24/06/20 14:48	POLICE REPORT PAGE 3		Load TIF	
7	24/06/20 16:50	INSURED CAR		Load JPG	☒
8	24/06/20 16:50	INSURED CAR		Load JPG	☒
9	24/06/20 16:50	INSURED CAR		Load JPG	☒
10	24/06/20 16:50	INSURED CAR		Load JPG	☒
11	24/06/20 16:50	INSURED CAR		Load JPG	☒
12	24/06/20 16:50	INSURED CAR		Load JPG	☒
13	24/06/20 16:50	INSURED CAR		Load JPG	☒
14	24/06/20 16:50	INSURED CAR		Load JPG	☒
15	24/06/20 16:50	INSURED CAR		Load JPG	☒
16	24/06/20 16:50	INSURED CAR		Load JPG	☒
17	24/06/20 16:50	INSURED CAR		Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST

ResetSavePrint

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To:

☐ Repairer

☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI20006713/USF3S2**Date:** 14/07/2020**REFERENCE**

Insured/Claimant:	MOHAMMAD AZFAR BIN HASHIM	Policy No:	DMPCSN3076441900		
Date of Loss:	23/06/2020	Nature of Claim:	OD	Claim No:	SNM20D202242/C01/TANGHL2

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGM1623U		Engine No:	EJ20C689388
Make & Model:	SUBARU FORESTER, 2.0 X (A)		Chassis No:	JF1SG5KE56G071865
Reg. Date:	10/10/2006 (Man. Year: 2006)		Odometer:	180252 km
Colour:	Red			
Engine Capacity:	1994 cc			
Market Value/New Car Price:	S\$9,000.00			
Sum Insured (S\$):	Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/55 R17	Rear Tyre Size:	215/55 R17
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	0.00	0.00	0.00	
- Excess (S\$)	1,500.00	1,500.00	0.00	0.00
Nett Amount (S\$)	-1,500.00	-1,500.00	0.00	0.00

INSPECTION

Date of Assignment:	26/06/2020	Present Location:	Car City Auto Centre Pte Ltd (HQ)
Date Inspected:	26/06/2020	Inspected At:	Car City Auto Centre Pte Ltd (HQ) Blk 9006 #01-198, Tampines Street 93 Singapore 528840
Estimated Period of Repair:	0.0 days		

Adjuster: MARCUS CHUA**Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

Market Value :	\$ 9,000.00
OMV :	\$ 18,137.00
PARF Rebate (1) :	\$ 0.00
Quota Premium Paid :	\$ 28,376.00
COE Rebate (2) :	\$ 7,278.00
Total Rebate (1) + (2) = :	\$ 7,278.00

The total amount incurred will be Market Value \$ 9,000.00 minus Total Rebate \$ 7,278.00
= \$ 1,722.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 13 Jul 2020)
Parts:	M1-SUV	SUBARU FORESTER 2.0 X (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGM1623U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >