LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd. From

3 Anson Road

#16-00 Springleaf Tower Singapore 079909 From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Ben Tang Date: 29 Jun 2020

Preliminary Advice

Vehicle No : SGM1623U Accident Date : 23/06/2020

Make : SUBARU FORESTER Policy No. : DMPCSN3076441900

Assignment Date : 26/06/2020 Excess : S\$1,500.00

Date of Inspection : 26/06/2020 Est. Duration of Repair : -

Inspection At : Car City Auto Centre Pte Ltd (HQ)

Blk 9006 #01-198, Tampines Street 93

Singapore 528840

Point of Impact / General Description of Damages

The vehicle sustained impact / damages o/s front & n/s front portion, n/s body and parts claimed are consistent to the accident. The undercarriage affected due to collision.

Repairer's Estimate (Gross) :S\$ TOTAL LOSS
Revised Amount :S\$ TOTAL LOSS
Check Items (Estimated) :S\$ TOTAL LOSS
Total :S\$ TOTAL LOSS

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

Pre-Accident Value :S\$ 9,000.00 COE / PARF Rebate :S\$ 7,278.00

Salvage Value :S\$

Margin for Repair :S\$ 1,722.00

Remarks

Other comments:

()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
(X)	The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck. Vehicle recommended total loss.