



CYCLE & CARRIAGE

CYCLE & CARRIAGE FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel 67461000 Fax 64875857



ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
MS First Capital Insurance Limited 36 Robinson Road #16-01 City House Singapore 068877	Cust No/Name KCV15407/Ms Lau Wan Heek Reg No/Reg Date SMS28498 / 20/02/2020 Date In/Mileage 24/06/2020/ 0 Chassis No GF7W0601806 Engine No 4J11BG2848 Make/Model MIT/19MY OUTLANDER 2.0 ELEG (995) Colour/Trim P02 / BK
Contact No	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000034	Credit	24/06/2020/ 14:37	DS	218 / MarsLer	47198
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M SUNDRY					+ 50.00
C & C LOGO					+ 50.00
M SUNDRY					+ 50.00
MIVEC EMBLEM					✓ 280.00
S MIPNT88088					✓ 250.00
REVERSE SENSOR SET					80 100.00
S MIPNT88088					✓ 250.00
DIAGNOSTIC / SCANNING					80 100.00
S MIPNT88088					✓ 250.00
TO CHECK LIGHTING AND WIRING SYSTEM ON REAR ACCIDENT AFFECTED AREAS					80 100.00
S MIPNT88088					✓ 250.00
TO REMOVE AND RE-INSTALL TRIMMING AND CAPERTING TO GIVE WAY ACCESS REPAIR ON REAR ACCIDENT AFFECTED AREAS					80 100.00
S MIPNT88088					✓ 250.00
TO REPLACE REAR BUMPER, LH REINFORCEMENT, ETC					80 100.00
-TO CUT & RE-WELD REAR END PANEL AND LH EXTENSION QTR PANEL					80 100.00
-TO REPAIR LHR OTR QTR PANEL					80 100.00
STRAIGHTEN, REFORM, ALIGN ON REAR ACCIDENT AFFECTED AREAS					80 100.00
S MIPNT88088					✓ 250.00
TO APPLY SEALANT KIT ON NEW PANEL					80 100.00
S MIPNT98088					✓ 250.00
SPRAY PAINTING ON REAR ACCIDENT AFFECTED AREAS					80 100.00
P JJ6410D734RA	FACE, RR BUMPER	1.00	1008.00	0.00	✓ 1008.00
P JJ6415A090HA	EXTENSION, RR BUMPER	1.00	360.00	0.00	✓ 360.00
P JJ6512A6B1	CLIP, RR BUMPER	30.00	6.00	0.00	✓ 180.00
P JJMR200300	CLIP, RR BUMPER	10.00	4.00	0.00	✓ 40.00
P JJ6410D336	LH SIDE BRACKET, RR	1.00	12.00	0.00	✓ 12.00
P JJ6410D337	RH SIDE BRACKET, RR	1.00	12.00	0.00	✓ 12.00
M JJ6410B895	LH REINFORCEMENT, RR	1.00	79.00	0.00	✓ 79.00
M JJ7407A317	LH MOULDING, RR BUMP	1.00	106.00	0.00	✓ 106.00
M JJ7407A647	LH MOULDING, RR WHEEL	1.00	160.00	0.00	✓ 160.00
M JJ7407A318	RH MOULDING, RP BUMP	1.00	106.00	0.00	✓ 106.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857

MITSUBISHI
MOTORS

ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
MS First Capital Insurance Limited 36 Robinson Road #16-01 City House Singapore 068877	Cust No/Name KCV15407/Ms Lau Wan Heek Reg No/Reg Date SMS2849B / 20/02/2020 Date In/Mileage 24/06/2020/ 0 Chassis No GF7W0601806 Engine No 4J118G2848 Make/Model MIT/19MY OUTLANDER 2.0 ELEG (995) Colour/Trim P02 / BK
Contact No	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	
F0000034	Credit	24/06/2020/ 14:37	DS	218 / MarsLer	47198	
Description of Goods / Services			Qty	Unit Price	Disc%	Amount
M	JJ5257A967	RR END PANEL <i>Reps</i>	1.00	246.00	0.00	+ 246.00
M	JJ5301F623	OTR LH EXTENSION QTR <i>Reps</i>	1.00	276.00	0.00	+ 276.00
M	JJ5301H593	RR LWR LH EXTENSION <i>Reps</i>	1.00	78.00	0.00	+ 78.00
M	JJ8336A153	LH REFLECTOR, TAIL L <i>Reps</i>	1.00	100.00	0.00	+ 100.00
P	JJ8330B173	RR LH LAMP ASSY, COM <i>encl.</i>	1.00	600.00	0.00	+ 600.00
P	JJ7415A401	MARK, OUTLANDER <i>Reps</i>	1.00	95.00	0.00	+ 95.00
Z	NOTES					
ACCIDENT ON 23/06/2020 ALONG TUNNEL OF CTE						
OWNER CLAIMING THIRD PARTY						
REQUIRED REPLACEMENT CAR						
TP # SHD3247U TP INS : MS FIRST CAPITAL						

Estimate

LKK Auto Consultants hence notify the Repairer of the following:

To resurvey before/after spray painting

To display damaged part(s) during resurvey

Parts prices are subject to confirmation

Third party survey is on a "Without Prejudice" basis

No illegal modification(s) is allowed

Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

18213836

Adnan Lj

P/1 30/06/20

04 Aug

Estimate

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adnan Lj
P/p 30/06/20
04 Day

Confirm & accepted by

Parts	3,458.00
Labour	0.00
Standard Menu	0.00
Specialist Job	7,730.00
Others(Lub,etc)	0.00
Sundry	100.00
Total(w/o GST)	11,288.00

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.