

**GBE7476P [GBH122R] - Submitted by: Appraisal VP Pte Ltd (HQ)**



**1/21: Rear View Right**



**2/21: Rear View**



**3/21: Rear View Left**

**GBE7476P [GBH122R] - Submitted by: Appraisal VP Pte Ltd (HQ).**



**4/21: Photographs of Damaged Items**



**5/21: Photographs of Damaged Items**



**6/21: Photographs of Damaged Items**



GBE7476P [GBH122R] - Submitted by: Appraisal VP Pte Ltd (HQ).



7/21: Photographs of Damaged Items



8/21: Photographs of Damaged Items



9/21: Photographs of Damaged Items

GBE7476P [GBH122R] - Submitted by: Appraisal VP Pte Ltd (HQ).



10/21: Photographs of Damaged Items



11/21: Photographs of Damaged Items



12/21: Photographs of Damaged Items



GBE7476P [GBH122R] - Submitted by: Appraisal VP Pte Ltd (HQ).



13/21: Photographs of Damaged Items




14/21: Photographs of Damaged Items



15/21: Photographs of Damaged Items

GBE7476P [GBH122R] - Submitted by: Appraisal VP Pte Ltd (HQ).



16/21: Odometer Reading



17/21: Chassis Number



18/21: Photo After Spray

**GBE7476P [GBH122R] - Submitted by: Appraisal VP Pte Ltd (HQ).**



**19/21: Photo After Spray**



**20/21: Photo After Spray**



**21/21: Photo After Spray**