

COMFORTDELDRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHA5745B

25/06/20

MAKE :

MODEL HYU- I40

CHIANG/NTUC

Qty	Parts Description/ Labour	TYPE	Unit Price	Amount
1	REAR BUMPER COVER			\$1,106.00
2	REAR BUMPER BRACKET SIDE LH/RH		\$35.60	\$71.20
10	REAR BUMPER CLIPS		\$2.20	\$22.00
1	REAR BUMPER REINFORCEMENT			\$428.40
1	REAR BUMPER UNDER COVER			\$228.00
1	REAR BUMPER REINFORCEMENT STAY		\$80.30	\$160.60
1	BOOTLID			\$2,174.90
1	BOOTLID CRDI PLATE			\$27.90
1	BOOTLID I-40 PLATE			\$21.10
SUB TOTAL			3351.90.	\$4,240.10
20.00%				\$848.02
DISCOUNTED TOTAL			2681.52.	\$3,392.08
1	BOOTLID COMFORT LOGO			\$30.00
1	BOOTLID COMFORT TEL NO			\$30.00
1	REVERSE SENSOR		NN X	\$135.70
1	REAR BUMPER MAT		90.	\$50.00
				\$245.70
Labour Charge				
Panel Beating				\$540.00
Spray Painting Charge				\$500.00
Remove/refix reverse sensor				\$60.00
Tuff Kote			910	\$60.00
Check Lighting				\$60.00
TOTAL LABOUR				\$1,220.00
ESTIMATE TOTAL				\$4,857.78
			3681.52	
			4/5/2950, 3 days	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Tanjin 97445744
 WP 25/6/20 2pm
 bumpson
 23 days
 Resurvey after repair
 tanjin @ Mhdanfaw

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: