

Veron Chen (LKKAUTO)

From: Rasul (LKKAUTO)
Sent: Friday, 17 July 2020 9:05 AM
To: Ivan Teo
Cc: Veron Chen (LKKAUTO)
Subject: RE: SJE5998T FINALISE

Hi Ivan,

Finalised amount of \$ 11,088.77 / 7 plus extra 2 days = 9 days of repair is confirmed

Note: We are on work from home arrangement. All correspondence should be made via email. Submission of claim related documents will be in softcopy. Any inconvenience caused is much regretted.

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Ivan Teo [mailto:ivanteo@honda.com.sg]
Sent: Thursday, 16 July, 2020 10:09 AM
To: Rasul (LKKAUTO)
Subject: RE: SJE5998T FINALISE

Hi Rasul,

There was no billing for the number plate.
I have revise the invoice with the item taken out.

Thank you

Warmest Regards

Ivan Teo
Kah Motor Co. Sdn Bhd
255 Alexandra Road
Singapore 159937
DID : 97317842
Email: ivanteo@honda.com.sg

From: Rasul (LKKAUTO) <Rasul@lkkauto.com>
Sent: Thursday, 16 July 2020 9:19 AM
To: Ivan Teo <ivanteo@honda.com.sg>
Subject: RE: SJE5998T FINALISE

Hi Ivan,

The number plate with casing I did not give this item, if damage kindly forward me the photo. no photo seen in your email that you sent to me

Note: We are on work from home arrangement. All correspondence should be made via email. Submission of claim related documents will be in softcopy. Any inconvenience caused is much regretted.

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Ivan Teo [<mailto:ivanteo@honda.com.sg>]

Sent: Wednesday, 15 July, 2020 3:33 PM

To: Rasul (LKKAuto)

Subject: SJE5998T FINALISE

Dear Rasul,

Kindly assist to finalise cost of repair \$11088.77
9 working days of repair.

Please note front bulkhead replace, additional 2 day of labour.

Thank you

Warmest Regards

Ivan Teo

Kah Motor Co. Sdn Bhd

255 Alexandra Road

Singapore 159937

DID : 97317842

Email: ivanteo@honda.com.sg



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from

disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.