



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722
Tel: 6457 5788 Fax: 6252 8459 Mobile: 9687 4031
Email: yeeautopte@td@gmail.com
Registration No: 201719251W GST No: 201719251W

M/S: AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16
Singapore 079120

ATTN: Motor Claim Department

Your Ref No: -
Claim Type: Third Party
Accident Date: 25/06/2020
TP Veh Reg No: SKV6053L

Estimate No: ES2000055

Date: 29 Jun 2020

Policy No:

Veh Reg No: SKZ3384E

Make/Model: TOYOTA ESTIMA
AERAS 2.4 A

Chassis No: ACR500105323

Engine No: 2AZC772559

Reg. Date: 26/01/2010

Estimate Repair Cost to Vehicle No :SKZ3384E

Description	U/Price	Quantity	List Price S\$	Amount S\$
Net Price				
1 REAR NUMBER PLATE	50.00	1 PC	50.00	X
2 REAR WINDSCREEN SEALANT	60.00	1 PC	60.00	40.00
3 REVERSE CAMERA	300.00	1 PC	300.00	X
4 REVERSE SENSORS	400.00	1 SET	400.00	✓
			810.00	810.00
Spare Parts				
5 REAR AIR VENT - LH	60.50	1 PC	60.50	X
6 REAR BUMPER	1,147.50	1 PC	1,147.50	✓
7 REAR BUMPER BRACKET - LH	132.20	1 PC	132.20	✓
8 REAR BUMPER BRACKET - RH	132.20	1 PC	132.20	X
9 REAR BUMPER CLIPS	50.00	1 SET	50.00	✓
10 REAR BUMPER REFLECTOR - LH	67.10	1 PC	67.10	✓
11 REAR BUMPER REFLECTOR - RH	67.10	1 PC	67.10	X
12 REAR BUMPER SIDE RETAINER - LH (FRONT)	77.80	1 PC	77.80	✓
13 REAR BUMPER SIDE RETAINER - LH (REAR)	77.80	1 PC	77.80	✓
14 REAR BUMPER SIDE RETAINER - RH (FRONT)	77.80	1 PC	77.80	X
15 REAR BUMPER SIDE RETAINER - RH (REAR)	77.80	1 PC	77.80	X
16 REAR BUMPER SPONGE - LH	79.80	1 PC	79.80	✓
17 REAR BUMPER SPONGE - RH	79.80	1 PC	79.80	X
18 REAR BUMPER TOWING COVER - LH	60.00	1 PC	60.00	✓
19 REAR BUMPER TOWING COVER - RH	60.00	1 PC	60.00	X
20 REAR BUZZER SENSOR	189.00	1 PC	189.00	X
21 REAR CHASSIS MEMBER - LH	950.80	1 PC	950.80	X
22 REAR ELECTRONICS ANTENNA SENSOR	198.00	1 PC	198.00	X
23 REAR END PANEL	560.94	1 PC	560.94	✓
24 REAR END PANEL INNER GARNISH	281.90	1 PC	281.90	✓
25 REAR END PANEL LOWER GARNISH	218.90	1 PC	218.90	✓
26 REAR END PANEL TOP GARNISH	288.90	1 PC	288.90	✓
27 REAR FENDER - LH	1,450.90	1 PC	1,450.90	✓
28 REAR FENDER GLASS MOULDING - LH	120.50	1 PC	120.50	✓
29 REAR FENDER INNER PANEL - LH	1,150.50	1 PC	1,150.50	X
30 REAR FENDER INNER SHIELD CLIP - LH	40.00	1 SET	40.00	X
31 REAR FENDER INNER SHIELD CLIP - RH	40.00	1 SET	40.00	X
32 REAR FENDER INNER TRIM - LH	658.20	1 PC	658.20	✓
33 REAR FENDER INNER TRIM - RH	658.20	1 PC	658.20	X
34 REAR FENDER WINDSCREEN SEALANT - LH	60.00	1 PC	60.00	40.00

Not Notified
11 Days & 8500k
Returning After Repair
12 days

601.20

981.25



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/07-12 Sin Ming AutoCity Singapore 575722
Tel: 6457 5788 Fax: 6252 8459 Mobile: 9687 4031
Email: yeeautopte@gmail.com
Registration No: 201719251W GST No: 201719251W

M/S: AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16
Singapore 079120

ATTN: Motor Claim Department

Your Ref No: -
Claim Type: Third Party
Accident Date: 25/06/2020
TP Veh Reg No: SKV6053L

Estimate No: ES2000055
Date: 29 Jun 2020
Policy No:
Veh Reg No: SKZ3384E
Make/Model: TOYOTA ESTIMA
AERAS 2.4 A
Chassis No: ACR500105323
Engine No: 2AZC772559
Reg. Date: 26/01/2010

Estimate Repair Cost to Vehicle No: SKZ3384E

Description	U/Price	Quantity	List Price	Amount
			SS	SS
35 REAR NUMBER PLATE LAMP - LH	102.40	1 PC	102.40	X
36 REAR NUMBER PLATE LAMP - RH	102.40	1 PC	102.40	X
37 REAR SPARE WHEEL PANEL	950.90	1 PC	950.90	X
38 REAR TAIL GATE STOPPER RUBBER - LH	35.00	1 PC	35.00	X
39 REAR TAIL GATE STOPPER RUBBER - RH	35.00	1 PC	35.00	X
40 REAR TAIL GATE WIPER MOTOR	485.50	1 PC	485.50	X
41 REAR TAILGATE	1,406.10	1 PC	1,406.10	X
42 REAR TAILGATE 'LOGO' EMBLEM	85.60	1 PC	85.60	X
43 REAR TAILGATE ABSORBER - LH	220.50	1 PC	220.50	X
44 REAR TAILGATE ABSORBER - RH	220.50	1 PC	220.50	X
45 REAR TAILGATE AUTO OPENING MOTOR	1,450.90	1 PC	1,450.90	X
46 REAR TAILGATE CENTRE REFLECTOR	307.80	1 PC	307.80	X
47 REAR TAILGATE EMBLEM 'AERAS'	68.50	1 PC	68.50	X
48 REAR TAILGATE EMBLEM 'ESTIMA'	68.50	1 PC	68.50	X
49 REAR TAILGATE INNER HOLDER	62.10	1 PC	62.10	X
50 REAR TAILGATE INNER OPENING SWITCH	185.50	1 PC	185.50	X
51 REAR TAILGATE INNER TRIM BOARD CLIPS	40.00	1 SET	40.00	X
52 REAR TAILGATE INNER TRIMBOARD	420.10	1 PC	420.10	X
53 REAR TAILGATE LOCK	355.90	1 PC	355.90	X
54 REAR TAILGATE LOCK COVER	59.30	1 PC	59.30	X
55 REAR TAILGATE OUTER GARNISH	320.20	1 PC	320.20	X
56 REAR TAILGATE OUTER OPENING SWITCH	185.10	1 PC	185.10	X
57 REAR TAILGATE REFLECTOR - LH	558.20	1 PC	558.20	X
58 REAR TAILGATE REFLECTOR - RH	558.20	1 PC	558.20	X
59 REAR TAILGATE WEATHERSTRIP	235.90	1 PC	235.90	X
60 REAR TAILLAMP PANEL - LH	289.20	1 PC	289.20	X
61 REAR WHEEL PANEL TOOL BOX	456.20	1 PC	456.20	X
62 REAR WHEEL PANEL TRIMBOARD	310.00	1 PC	310.00	X
63 REAR WINDSCREEN MOULDING	134.41	1 PC	134.41	X
64 REAR WIPER BLADE	45.20	1 PC	45.20	X
65 REAR WIPER MOTOR	568.20	1 PC	568.20	X
66 SPARE WHEEL TOP COVER	385.15	1 PC	385.15	X
67 TAIL LAMP LH	626.20	1 PC	626.20	X
68 TAIL LAMP RH	626.20	1 PC	626.20	X
			21,075.00	21,075.00

Labour

206.20

117.95

108



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/07-12 Sin Ming AutoCity Singapore 575722
Tel: 6457 5768 Fax: 6252 8450 Mobile: 9887 4031
Email: yeeautopte@gmail.com
Registration No: 201719251W GST No: 201719251W

M/S: AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16
Singapore 079120

ATTN: Motor Claim Department

Your Ref No: .
Claim Type: Third Party
Accident Date: 25/06/2020
TP Veh Reg No: SKV6053L

Estimate No: ES2000055
Date: 29 Jun 2020
Policy No:
Veh Reg No: SKZ3384E
Make/Model: TOYOTA ESTIMA
AERAS 2.4 A
Chassis No: ACR500105323
Engine No: 2AZC772559
Reg. Date: 26/01/2010

Estimate Repair Cost to Vehicle No: SKZ3384E

Description	U/Price	Quantity	List Price S\$	Amount S\$
69 TO DISMANTLE & REPLACE DAMAGED PARTS. PANEL BEAT WHERE NECESSARY.	2,200.00	1 JOB	2,200.00	1600
70 TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	1,800.00	1 JOB	1,800.00	1200
71 TO APPLY RUST-PROOFING ON REPAIRED, REPLACED PANEL.	200.00	1 JOB	200.00	90
72 TO REMOVE/REFIT REAR WINDSCREEN TO FACILITATE REPAIRS.	200.00	1 JOB	200.00	120
73 TO REMOVE/REFIT REAR PASSENGER SEAT, FENDER GARNISHES TO FACILITATE REPAIRS.	250.00	1 JOB	250.00	120
74 TO REMOVE/TRANSFER TAILGATE COMPONENTS.	180.00	1 JOB	180.00	60
75 TO CHECK WIRING FUNCTIONS.	80.00	1 JOB	80.00	20
76 COMPUTER DIAGNOSTIC RESET.	280.00	1 JOB	280.00	7
77 TO TOW VEHICLE TO WORKSHOP.	120.00	1 JOB (9.11)	120.00	2
78 WHEEL ALIGNMENT.	120.00	1 T	120.00	X
79 TO REMOVE REAR FENDER GLASS & TAILGATE GLASS LABOUR.	0.00	1 JOB	120.00	60

5,430.00 5,430.00

Total S\$ 27,315.00

Add GST @ 7% 1,912.05

Total Amount Payable S\$ 29,227.05

TOTAL: SINGAPORE DOLLAR TWENTY NINE THOUSAND TWO HUNDRED TWENTY SEVEN AND CENTS FIVE ONLY

LK's Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

For Yee Auto Pte Ltd

AUTHORISED SIGNATURE