

ASS. REC. BY:

REF:

AIG /

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

12

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP / 24 HRS

10/28

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKZ 3384E

Yr Regn:

01, 10

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA)

Wagon

Make:

Toy

Estime

c.c

2362

Colour

M. Silver

A/C:

Insured / Std / NI / NA

Sp. Reading

224576

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

ACR 50

0105323

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: NII / SRM / STD A/Rlm or

Tyre Size:

F: Falken

R:

Pir 245/40R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / (PIR) SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

8

mm

R/Bal.

7

mm

L/Bal.

8

mm

L/Bal.

7

mm

D.O.A.

25/6/20

D.O.I.

29/6/2020

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Rear N/S

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

S - RS, SI

Fees

Others

Report Format :

Lump Sum / I.B.I: (\$

TOTAL



# YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722  
Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031  
Email: yeeautopte ltd@gmail.com  
Registration No.: 201719251W GST No: 201719251W

M/S : AIG Asia Pacific Insurance Pte Ltd  
78 Shenton Way  
#07-16  
Singapore 079120

ATTN: Motor Claim Department

Your Ref No: -  
Claim Type: Third Party  
Accident Date: 25/06/2020  
TP Veh Reg No: SKV6053L

Estimate No: ES2000055  
Date: 29 Jun 2020  
Policy No:  
Veh Reg No: SKZ3384E  
Make/Model: TOYOTA ESTIMA  
AERAS 2.4 A  
Chassis No: ACR500105323  
Engine No: 2AZC772559  
Reg. Date: 26/01/2010

*Not Notified*  
*6 Days & ?*  
*Returning After Pain*  
*12 days*

## Estimate Repair Cost to Vehicle No :SKZ3384E

Description	U/Price	Quantity	List Price SS	Amount SS
<b>Net Price</b>				
1 REAR NUMBER PLATE	50.00	1 PC	<i>Sn</i> 50.00	X
2 REAR WINDSCREEN SEALANT	60.00	1 PC	<i>Ma</i> 60.00	<i>40.50</i>
3 REVERSE CAMERA	300.00	1 PC	<i>Sn</i> 300.00	X
4 REVERSE SENSORS	400.00	1 SET	<i>Ma</i> 400.00	<i>✓</i>
			810.00	810.00
<b>Spare Parts</b>				
5 REAR AIR VENT -LH	60.50	1 PC	<i>Sn</i> 60.50	X
6 REAR BUMPER	1,147.50	1 PC	<i>B</i> 1,147.50	<i>✓</i>
7 REAR BUMPER BRACKET - LH	132.20	1 PC	<i>B</i> 132.20	<i>✓</i>
8 REAR BUMPER BRACKET - RH	132.20	1 PC	<i>B</i> 132.20	X
9 REAR BUMPER CLIPS	50.00	1 SET	<i>Ma</i> 50.00	<i>✓</i>
10 REAR BUMPER REFLECTOR - LH	67.10	1 PC	<i>CM</i> 67.10	<i>✓</i>
11 REAR BUMPER REFLECTOR - RH	67.10	1 PC	<i>Sn</i> 67.10	X
12 REAR BUMPER SIDE RETAINER - LH (FRONT)	77.80	1 PC	<i>CM</i> 77.80	<i>✓</i>
13 REAR BUMPER SIDE RETAINER - LH (REAR)	77.80	1 PC	<i>Di</i> 77.80	<i>✓</i>
14 REAR BUMPER SIDE RETAINER - RH (FRONT)	77.80	1 PC	<i>Sn</i> 77.80	X
15 REAR BUMPER SIDE RETAINER - RH (REAR)	77.80	1 PC	<i>Sn</i> 77.80	X
16 REAR BUMPER SPONGE - LH	79.80	1 PC	79.80	?
17 REAR BUMPER SPONGE - RH	79.80	1 PC	<i>Sn</i> 79.80	X
18 REAR BUMPER TOWING COVER - LH	60.00	1 PC	<i>Ma</i> 60.00	<i>✓</i>
19 REAR BUMPER TOWING COVER - RH	60.00	1 PC	<i>Sn</i> 60.00	X
20 REAR BUZZER SENSOR	189.00	1 PC	189.00	?
21 REAR CHASSIS MEMBER - LH	950.80	1 PC	950.80	?
22 REAR ELECTRONICS ANTENNA SENSOR	198.00	1 PC	198.00	?
23 REAR END PANEL	560.94	1 PC	<i>B</i> 560.94	<i>✓</i>
24 REAR END PANEL INNER GARNISH	281.90	1 PC	<i>Di</i> 281.90	<i>✓</i>
25 REAR END PANEL LOWER GARNISH	218.90	1 PC	218.90	?
26 REAR END PANEL TOP GARNISH	288.90	1 PC	288.90	?
27 REAR FENDER - LH	1,450.90	1 PC	<i>Bu</i> 1,450.90	<i>✓</i>
28 REAR FENDER GLASS MOULDING - LH	120.50	1 PC	<i>Ma</i> 120.50	<i>✓</i>
29 REAR FENDER INNER PANEL - LH	1,150.50	1 PC	<i>R</i> 1,150.50	X
30 REAR FENDER INNER SHIELD CLIP - LH	40.00	1 SET	<i>Ma</i> 40.00	X
31 REAR FENDER INNER SHIELD CLIP - RH	40.00	1 SET	<i>Ma</i> 40.00	X
32 REAR FENDER INNER TRIM - LH	658.20	1 PC	<i>Bu</i> 658.20	<i>✓</i>
33 REAR FENDER INNER TRIM - RH	658.20	1 PC	<i>Sn</i> 658.20	X
34 REAR FENDER WINDSCREEN SEALANT - LH	60.00	1 PC	<i>Ma</i> 60.00	<i>40.50</i>





# YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722  
Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031  
Email: yeeautopte ltd@gmail.com  
Registration No.: 201719251W GST No: 201719251W

M/S : AIG Asia Pacific Insurance Pte Ltd  
78 Shenton Way  
#07-16  
Singapore 079120

ATTN: Motor Claim Department

Your Ref No: -  
Claim Type: Third Party  
Accident Date: 25/06/2020  
TP Veh Reg No: SKV6053L

Estimate No: ES2000055  
Date: 29 Jun 2020  
Policy No:  
Veh Reg No: SKZ3384E  
Make/Model: TOYOTA ESTIMA  
AERAS 2.4 A  
Chassis No: ACR500105323  
Engine No: 2AZC772559  
Reg. Date: 26/01/2010

## Estimate Repair Cost to Vehicle No :SKZ3384E

Description	U/Price	Quantity	List Price	Amount
			SS	SS
35 REAR NUMBER PLATE LAMP - LH	102.40	1 PC	Sn 102.40	X
36 REAR NUMBER PLATE LAMP - RH	102.40	1 PC	Sn 102.40	X
37 REAR SPARE WHEEL PANEL	950.90	1 PC	950.90	?
38 REAR TAIL GATE STOPPER RUBBER - LH	35.00	1 PC	Sn 35.00	X
39 REAR TAIL GATE STOPPER RUBBER - RH	35.00	1 PC	Sn 35.00	X
40 REAR TAIL GATE WIPER MOTOR	485.50	1 PC	Sn 485.50	X
41 REAR TAILGATE	1,406.10	1 PC	Sn 1,406.10	✓
42 REAR TAILGATE 'LOGO' EMBLEM	85.60	1 PC	Sn 85.60	✓
43 REAR TAILGATE ABSORBER - LH	220.50	1 PC	Sn 220.50	X
44 REAR TAILGATE ABSORBER - RH	220.50	1 PC	Sn 220.50	X
45 REAR TAILGATE AUTO OPENING MOTOR	1,450.90	1 PC	Sn 1,450.90	X
46 REAR TAILGATE CENTRE REFLECTOR	307.80	1 PC	Sn 307.80	X
47 REAR TAILGATE EMBLEM 'AERAS'	68.50	1 PC	Sn 68.50	✓
48 REAR TAILGATE EMBLEM 'ESTIMA'	68.50	1 PC	Sn 68.50	✓
49 REAR TAILGATE INNER HOLDER	62.10	1 PC	Sn 62.10	X
50 REAR TAILGATE INNER OPENING SWITCH	185.50	1 PC	Sn 185.50	X
51 REAR TAILGATE INNER TRIM BOARD CLIPS	40.00	1 SET	Sn 40.00	✓
52 REAR TAILGATE INNER TRIMBOARD	420.10	1 PC	Sn 420.10	✓
53 REAR TAILGATE LOCK	355.90	1 PC	Sn 355.90	✓
54 REAR TAILGATE LOCK COVER	59.30	1 PC	Sn 59.30	X
55 REAR TAILGATE OUTER GARNISH	320.20	1 PC	Sn 320.20	?
56 REAR TAILGATE OUTER OPENING SWITCH	185.10	1 PC	Sn 185.10	X
57 REAR TAILGATE REFLECTOR - LH	558.20	1 PC	Sn 558.20	X
58 REAR TAILGATE REFLECTOR - RH	558.20	1 PC	Sn 558.20	X
59 REAR TAILGATE WEATHERSTRIP	235.90	1 PC	Sn 235.90	50% Sn
60 REAR TAILLAMP PANEL - LH	289.20	1 PC	Sn 289.20	✓
61 REAR WHEEL PANEL TOOL BOX	456.20	1 PC	456.20	?
62 REAR WHEEL PANEL TRIMBOARD	310.00	1 PC	310.00	?
63 REAR WINDSCREEN MOULDING	134.41	1 PC	Sn 134.41	✓
64 REAR WIPER BLADE	45.20	1 PC	Sn 45.20	X
65 REAR WIPER MOTOR	568.20	1 PC	Sn 568.20	X
66 SPARE WHEEL TOP COVER	385.15	1 PC	Sn 385.15	X
67 TAIL LAMP LH	626.20	1 PC	626.20	?
68 TAIL LAMP RH	626.20	1 PC	Sn 626.20	X
			21,075.00	21,075.00

Labour





# YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722  
Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031  
Email: yeeautopte ltd@gmail.com  
Registration No.: 201719251W GST No: 201719251W

M/S : AIG Asia Pacific Insurance Pte Ltd  
78 Shenton Way  
#07-16  
Singapore 079120

ATTN: Motor Claim Department

Your Ref No: -  
Claim Type: Third Party  
Accident Date: 25/06/2020  
TP Veh Reg No: SKV6053L

Estimate No: ES2000055  
Date: 29 Jun 2020  
Policy No: SKZ3384E  
Veh Reg No: TOYOTA ESTIMA  
Make/Model: AERAS 2.4 A  
Chassis No: ACR500105323  
Engine No: 2AZC772559  
Reg. Date: 26/01/2010

## Estimate Repair Cost to Vehicle No :SKZ3384E

Description	U/Price	Quantity	List Price SS	Amount SS
69 TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY.	2,200.00	1 JOB	2,200.00	1600
70 TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	1,800.00	1 JOB	1,800.00	1200
71 TO APPLY RUST- PROOFING ON REPAIRED, REPLACED PANEL.	200.00	1 JOB	200.00	90
72 TO REMOVE/REFIT REAR WINDSCREEN TO FACILITATE REPAIRS.	200.00	1 JOB	200.00	120
73 TO REMOVE/REFIT REAR PASSENGER SEAT, FENDER GARNISHES TO FACILITIES REPAIRS.	250.00	1 JOB	250.00	120
74 TO REMOVE/TRANSFER TAILGATE COMPONENTS.	180.00	1 JOB	180.00	60
75 TO CHECK WIRING FUNCTIONS.	80.00	1 JOB	80.00	20
76 COMPUTER DIAGNOSTIC RESET.	280.00	1 JOB	280.00	?
77 TO TOW VEHICLE TO WORKSHOP.	120.00	1 JOB (B.I.I)	120.00	?
78 WHEEL ALIGNMENT	120.00	1 T	120.00	x
79 TO REMOVE REAR FENDER GLASS & TAILGATE GLASS LABOUR.	0.00	1 JOB	120.00	60
			5,430.00	5,430.00

Total SS 27,315.00

Add GST @ 7% 1,912.05

Total Amount Payable SS 29,227.05

TOTAL: SINGAPORE DOLLAR TWENTY NINE THOUSAND TWO HUNDRED TWENTY SEVEN AND CENTS FIVE ONLY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

For Yee Auto Pte Ltd

AUTHORISED SIGNATURE

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	26/06/2020 10:48
Date Of Accident	25/06/2020 13:50
Exact Location Of Accident	UPPER CHANGI RD EAST TWDS BEDOK RD CROSS JUNCTION
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKZ3384E
<b>Insured/Policyholder</b>	
Name Of Registered Owner	CHING CHIAT FONG
NRIC No	SXXXX722A
Email Address	BIGAPP7@GMAIL.COM
Mobile Phone No	(LOCAL) +65-90128222
Alternative Phone No	OFFICE-90128222

### Vehicle Particulars

Manufacturer	TOYOTA
Model	ESTIMA
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5116009418
Cover Note Number	

### Driver

Name of Driver	ARTHUR GAN TEE LEH
NRIC No	SXXXX953D
Date Of Birth	01/03/1960
Occupation	INDOOR
Date Of Driving Pass	10/03/1980
Driving Experience	40 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90128222
Fax Number	
Contact Number	OFFICE-90128222
Email Address	BIGAPP7@GMAIL.COM



Address 24 MERAGI ROAD  
SINGAPORE  
487902  
Postcode  
Was driver an employee of the Insured's Company NO  
If No, Relationship of the Driver with the Insured SPOUSE  
Vehicle Registration Number of Driver's Own Vehicle -  
Vehicle -  
Insurance Company of Driver's Own Vehicle -

#### General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR  
Weather Conditions CLEAR  
Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO  
Number of vehicles (including own vehicle) involved in the accident 2  
Was any body injured in the Accident? YES  
Was any injured conveyed to hospital by ambulance? NO  
Was any other material or property damaged? YES  
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
Number of Passengers (Including Driver) 2  
Passenger 1 NAME: : CHING CHIAT FONG  
GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police? YES  
If Yes, Please state which Police Station  
Police Station Name THOMSON NEIGHBOURHOOD POLICE POST  
Police Station Address ROAD: BLK 25 SIN MING ROAD , POSTCODE: 570025 , COUNTRY: SINGAPORE  
Police Station Contact TEL NO: 1800-4529999 - FAX NO: 6 5535740  
Was notice of intended Prosecution given? NO  
If Yes, against whom?

#### Circumstances of Accident

REFER TO ATTACHED

#### Attachment(s)

Are accident photos available for attachment? YES  
Was there any video captured by Car Camera? NO  
Was there any audio recorded? NO


#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SKV6053L  
Vehicle Make/Model/Colour  
Details Of Properties  
Vehicle Category PRIVATE CAR  
Name of Driver  
NRIC/Passport Number  
Contact Number

SKETCH PLAN

(A) SKZ 3384 E

(B) SKV6053 L



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to Police Report

Police Report No: T/20200625/2089

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:





**SINGAPORE  
POLICE FORCE**

Police Station Of Origin:  
Thomson NPP  
25 Sin Ming Road #01-180 SINGAPORE  
570025  
Tel No: 1800-4529999



T/20200625/2089

2 of 3

Report No. T/20200625/2089

## CONTINUATION OF REPORT

<b>Driver</b>			
Name	LEE JUNE		ID No. S8016633H
Related Vehicle	SKV6053L (Car)		Contact No. 98368002
Hospital/Clinic	NIL		Class of Driving Licence & Expiry Date Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Discharge	NIL
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL
<b>Driver</b>			
Name	ARTHUR GAN TEE LEH		ID No. S1450953D
Related Vehicle	SKZ3384E (Car)		Contact No. 90128222
Hospital/Clinic	MOUNT ALVERNIA HOSPITAL		Class of Driving Licence & Expiry Date Class: 3 Date of Expiry: NIL
Date Treatment	25/06/2020	Date Discharge	25/06/2020
No. of Days granted Medical Leave	05	Degree of Injury	Slight

**Brief Details.**

On 25/06/2020 at about 1350hrs, I was travelling in my vehicle (SKZ3384E) along Upper Changi Road East. I was turning right into Bedok road, however the traffic light was red at that time, thus my vehicle is at stationary. Few minutes later the main traffic light turns green but the right arrow was still red. A vehicle (SKV6053L) from my rear knocked onto my vehicle. Both the driver and I came out from our vehicle to exchange particulars and took some pictures of the accident. After which we left the incident location. Awhile later, I felt a slight pain around my neck area which led me to Mount Alvernia Hospital to consult a doctor. I was given 5 days MC after that.

No police or ambulance was at scene when the incident happened. I wish to add that there is no installed camera in my vehicle.

I am lodging this report for insurance claim purpose.