

CS3/FCI19007472/T1yf3-7

TAKING

ASS. REC. BY:

REF

CS3/FCI19007472/T1yf3-7

Special Instruction:

Surveyor: Tau Fien

Eric Woo

ASSIGNMENT (Office)

22.06.2020

From (Person):

Hang Koo

of

FC1

Date/Time:

29.4.19 12.51pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKB 3057B

Insured:

SHD 8507L

at Workshop m/s

Kok Wang CAG

Tel:

91839633

of

1 Soon Lu Street #06-40

Policy No:

Claim No:

D19002751MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

23.4.2019

CA / REV / REP. / REV 24 HRS

"wp"

H.O.D. Endorsement:

Date/Time:

29.4.19 1.43pm

Person Contacted:

MR Kok

Vehicle IN/OUT

Date/Time

Action/Instruction

Estimate (X)

SKB 3057B - X

SHD 8507L - CS / FCI 18003787 / Agd 3m2

D.O.A - 21/07/2018

Dismantle: 8/5/2019

After repair: 13/5/2019

29/06/2020 Eric said only want repair range & days they do not want survey report.

07/07/2020 RANGE OF REPAIR \$4500 - \$5500 REPAIR 6-7 DAYS