



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

EQ INSURANCE COMPANY LTD

INV No. AC2105983

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEX
SINGAPORE 069110

INV Date 24/08/2021
Reference CC4/EQI20006749/R1gs3q2
Code EQI

PROFESSIONAL SERVICE FEE

Vehicle No. SKV 8763H
Insured Veh. GBF 7327G
Claim No. DM20HO00943/SG
Policy No. DMCPHQ20- 000559
Accident Date 24/06/2020
Inspection Date 29/06/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
EQ INSURANCE COMPANY LTD 5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEXSINGAPORE 069110			Ref: CC4/EQI20006749/R1gs3q2 Date: 24/08/2021 Code: EQI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBF 7327G	Veh. Inspected	SKV 8763H	
Policy No.	DMCPHQ20- 000559	Coverage (\$)	0.00	
Claim No.	DM20HO00943/SG	Excess (\$)	0.00	
Assign From		Assign Date	29/06/2020	
2. Vehicle Particulars & Condition				
Make & Model	HONDA VEZEL 1.5X CVT	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	L15B4022906	Colour	WHITE	
Odometer	112640 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	DUNLOP	6 mm	
L/H Front Tyre	215/60 R16	DUNLOP	6 mm	
R/H Rear Tyre	215/60 R16	DUNLOP	6 mm	
L/H Rear Tyre	215/60 R16	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	24/06/2020	Inspection Date	29/06/2020	
Survey held at	XINYA AUTO SERVICES PTE LTD BLK 1002 BUKIT MERAH LANE 3 #01-75 SINGAPORE 159719			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			7 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKV 8763H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	DEFORMED	927.50	927.50
1	FRONT BUMPER RETAINER LH	NECESSARY	20.60	20.60
1	FRONT BUMPER REINFORCEMENT	SERVICEABLE	321.00	-
1	FRONT BUMPER BRACKET	NECESSARY	32.00	32.00
1	HEADLAMP LH	BROKEN	1,710.50	1,710.50
1	HEADLAMP BRACKET	CRACKED	35.20	35.20
1	HEADLAMP BALLAST	SERVICEABLE	780.00	-
1	FRONT FENDER LH	BENT	558.70	558.70
1	FRONT FENDER LH COWLING	DEFORMED	130.10	130.10
1	FRONT BONNET	BENT	892.35	892.35
1	FRONT BONNET UNDER COVER	TORN	122.30	122.30
10	COWLING & BUMPER CLIPS	NECESSARY	65.50	65.50
10	UNDER COVER CLIPS	SERVICEABLE	65.50	-
1	BONNET HINGES LH	BENT	48.50	48.50
4	BONNET RUBBER	NECESSARY	150.20	150.20
1	WIPER GARNISH	DEFORMED	240.15	240.15
1	BATTERY TRAY	SERVICEABLE	65.00	-
	LESS 20% DISCOUNT		-1,233.02	-986.72
			4,932.08	3,946.88
<u>SPECIAL NETT ITEMS</u>				
1	BATTERY (SN)	NOT NECESSARY	280.00	-
			280.00	-
<u>LABOUR</u>				
	TO REMOVE & REPLACE FRONT LH FENDER ,BONNET ,BUMPER ,ENFORCEMENT AND TO PANEL BEAT ALIGN BODY CHASSIS PANEL.		1,600.00	800.00
	TO PUTTY & SPRAY PAINT FRONT BONNET ,FENDER ,BUMPER AND OTHER AFFECTED AREA (PEARL WHITE).		1,200.00	800.00
	TO CHECK & RECTIFY WIRING & FOCUS HEADLAMP .		80.00	30.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TUFF KOTE.		250.00	80.00
			3,130.00	1,710.00
GRAND TOTAL			8,342.08	5,656.88
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,500.00

Report Ref No. CC4/EQI20006749/R1gs3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKV 8763H

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R






LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKV 8763H

RE-INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

