

XINYA AUTO SERVICES PTE LTD

Address: BLK 1002 BUKIT MERAH LANE 3 # 01-75 SINGAPORE 159719

E-mail : xinyaauto@singnet.com.sg

Tel: 6270 3481 Fax: 6278 7522

Date : 25/06/2020

Address : TAN LEONG SENG
BLK 4 TANJONG PAGAR PLAZA
#16-20
SINGAPORE 081004

Reference : TP 1247/06/20
Vehicle No : SKV 8763H
Make/Model : HONDA VEZEL
Insurance Co. : NTUC

RE : QUOTATION TO SKV 8763H FOR THIRD PARTY CLAIMS.

<u>PARTS REQUIRED</u>		<u>QTY</u>	<u>AMT \$</u>	
1)	FRONT BUMPER <i>de</i>	1	\$	927.50
2)	FRONT BUMPER RETAINER LH <i>ne</i>	1	\$	20.60
3)	FRONT BUMPER ENFORCEMENT <i>X</i>	1	\$	321.00 <i>X</i> SVC
4)	FRONT BUMPER BRACKET <i>ne</i>	1	\$	32.00
5)	HEADLAMP LH <i>bro</i>	1	\$	1,710.50
6)	HEADLAMP BRACKET <i>cm</i>	1	\$	35.20
7)	HEADLAMP BALLAST <i>X</i>	1	\$	780.00 <i>X</i> SVC
8)	FRONT FENDER LH <i>bt</i>	1	\$	558.70
9)	FRONT FENDER LH COWLING <i>de</i>	1	\$	130.10
10)	FRONT BONNET <i>bt</i>	1	\$	892.35
11)	FRONT BONNET UNDER COVER <i>turn</i>	1	\$	122.30
12)	COWLING & BUMPER CLIPS <i>ne</i>	10	\$	65.50
13)	UNDER COVER CLIPS <i>ne X</i>	10	\$	65.50 <i>X</i> SVC
14)	BONNET HINGES LH <i>bt</i>	1	\$	48.50
15)	BONNET RUBBER <i>ne</i>	4	\$	150.20
16)	WIPER GARNISH <i>de</i>	1	\$	240.15
17)	BATTERY TRAY <i>?</i>	1	\$	65.00 <i>X</i> SVC
LIST PRICE TOTAL			\$	6,165.10 <i>4933.60</i>
LESS DISCOUNT 20%			\$	1,233.02 <i>20%</i>
LIST PRICE TOTAL AFTER LESS			\$	4,932.08 <i>3946.88</i>
18)	BATTERY <i>?</i>		\$	280.00 <i>200?</i> <i>X</i> NN
NETT PRICE TOTAL				\$280.00
TOTAL PARTS COST				\$5,212.08

LABOUR AND MISCELLANEOUS CHARGES

- | | | |
|----|--|--|
| 1) | TO REMOVE & REPLACE FRONT LH FENDER, BONNET, BUMPER, ENFORCEMENT AND TO PANEL BEAT ALIGN BODY CHASSIS PANEL. | \$ 1,800.00 800
(8 DAYS) |
| 2) | TO PUTTY & SPRAY PAINT FRONT BONNET, FENDER, BUMPER AND OTHER AFFECTED AREA. (PEARL WHITE) | \$ 1,200.00 800
(6 PANELS) |
| 3) | TO CHECK & RECTIFY WIRING & FOCUS HEADLAMP. | \$ 80.00 30 |
| 4) | TUFF KOTE | \$ 250.00 80 |

LABOUR TOTAL

\$ 3,130.00

TOTAL ESTIMATED REPAIR COST

\$ 8,062.08

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Resul

By 20010568

7 days

4/8

29/06/2020 @ 1010

Resurvey after repair

3946.88

17101.00

5656.88

20%

4525.50

45 - 4500

7 days