

Not Actual
 dls
 1/2 = 4600
 Steps

29/6/20
 Take the other up

Vehicle:

GBG2194A

Make & Model:

Toyota Hiace

Chassis No:

S/N	Parts/Labour	QTY	Unit Price	Price	Recommend
1	Rear Tailgate			\$ 1,718.40	3 only ✓
2	Rear Tailgate View Mirror			\$ 312.80	1 x
3	Rear Tailgate Glass Sealant			\$ 60.00 SN	re 40 s. not
4	Emblem			\$ 59.00	re ✓
5	Hiace Sticker			\$ 56.00	re ✓
6	1250 Kg Sticker			\$ 48.00	re ✓
7	Rear Tailgate Lock			\$ 298.40	1 mi/jm ✓
8	Rear Right Taillamp		366.00	\$ 487.50	scn ✓
9	Rear Right Corner panel Garnish			\$ 128.40	re ✓
10	Rear Right Corner panel Retainer			\$ 95.80	re x
11	Rear End Panel		788.10	\$ 1,275.00	re 300 ✓
12	Rear End Panel Stricker			\$ 95.00	re x
13	Rear Bumper			\$ 687.40	re ✓
14	Rear Bumper Chips			\$ 30.00 SN	re ✓
15	Rear Bumper Retainer (Left & Right)	2	\$88.50	\$ 177.00	re x ✓
16	Rear Bumper Inner ^{Step} bracket			\$ 316.80	re ✓
17	Right Air Ventilation Duct			\$ 85.80	re x
18	Taillamp Lower Panel 0/5			\$ 296.00	re ✓
19	Rear Exhaust Pipe			\$ 583.60	2 x
20	Reverse sencer		1 set	\$ 200.00 SN	shad ✓
21	Panel Joint Sealant			\$ 60.00 SN	re 50
22	Tailgate weatherstrip			295.10	1 mi ✓
23					

S. not
 S. not

252

Labour				
1	Transfer Rear Glass		\$ 120.00	100
2	Transfer Tailgate		\$ 150.00	60
3	Transfer Glass Remove & Fitting Exhaust Pipe		\$ 80.00	11X
4	Check Wiring		\$ 80.00	20
5	Anti Rust Proofing		\$ 100.00	60
6	Panel Beaing		\$ 1,200.00	800
7	Paint Work		\$ 1,200.00	700
8				
9				

STYTECH AUTO PTE. LTD.

2 Kaki Bukit Ave 2 #02-00 0103
 Kaki Bukit Autohub Singapore 417921
 Tel: 6444 8125 Fax: 6445 3310
 GST Reg. No.: 201601539K
 Co. Reg. No.: 201601539K

Email: stytechent@singnet.com.sg

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

P- 4953.00
 252
 P- 3715.2
 S.W- 320.00
 L- 1740.00
 5775.2
 4620: