

Vehicle:

GBG2194A

not actual
dles
2/3
5 days

Make & Model:

29/6/20

Take photo after repair

Toyota Hiace

Chassis No:

S/N	Parts/Labour	QTY	Unit Price	Price	Recommend
1	Rear Tailgate			\$ 1,718.40	only on ✓
2	Rear Tailgate View Mirror			\$ 312.80	1 x ✓
3	Rear Tailgate Glass Sealant			\$ 60.00 SN	re 40 s. net ✓
4	Emblem			\$ 59.00	re ✓
5	Hiace Sticker			\$ 56.00	re ✓
6	1250 Kg Sticker			\$ 48.00	re ✓
7	Rear Tailgate Lock			\$ 298.40	2w/jm ✓
8	Rear Right Taillamp			\$ 487.50	scr ✓
9	Rear Right Corner panel Garnish			\$ 128.40	DD ✓
10	Rear Right Corner panel Retainer			\$ 95.80	1 x ✓
11	Rear End Panel			\$ 1,275.00	2x 500 ✓
12	Rear End Panel Stricker			\$ 95.00	1 x ✓
13	Rear Bumper			\$ 687.40	Dis ✓
14	Rear Bumper Chips			\$ 30.00 SN	re ✓
15	Rear Bumper Retainer (Left & Right)	2	\$88.50	\$ 177.00	o/s Bent 1 pc
16	Rear Bumper Inner ^{Step} Step bracket			\$ 316.80	sent ✓
17	Right Air Ventilation Duct			\$ 85.80	1 x ✓
18	Taillamp Lower Panel o/s			\$ 296.00	sent ✓
19	Rear Exhaust Pipe			\$ 583.60	2 x ✓
20	Reverse sencer		1 set	\$ 200.00 SN	shhd ✓
21	Panel Joint Sealant			\$ 60.00 SN	re 50
22	Tailgate weatherstrip			295.10	2w ✓
23					

Labour					
1	Transfer Rear Glass			\$ 120.00	100
2	Transfer Tailgate			\$ 150.00	60
3	Transfer Glass Remove & Fitting Exhaust Pipe			\$ 80.00	11X
4	Check Wiring			\$ 80.00	20
5	Anti Rust Proofing			\$ 100.00	60
6	Panel Beaing			\$ 1,200.00	800
7	Paint Work			\$ 1,200.00	700
8					
9					

STYTECH AUTO PTE. LTD.

2 Kaki Bukit Ave 2 #02-00 0103
 Kaki Bukit Autohub Singapore 417921
 Tel: 6444 8125 Fax: 6445 3310
 GST Reg. No.: 201601539K
 Co. Reg. No.: 201601539K

Email: stytechent@singnet.com.sg

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: