LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd. 5 Temasek Boulevard #04-01 Suntec Tower Five Singapore 038985 From: LKK Auto Consultants Pte Ltd 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Attn: Date: 07 Jul 2020

Preliminary Advice

Insured Vehicle No : GX6450X

TP Vehicle No : SMM9840K Accident Date : 29/06/2020 Make : HONDA FIT Assignment Date : 29/06/2020

Date of Inspection : 29/06/2020 Est. Duration of Repair : 12

Inspection At : FASTECH AUTO PTE LTD (HQ)

1 KAKI BUKIT AVE 6, #01-46/48/50 AUTOBAY

SINGAPORE 417883

Point of Impact / General Description of Damages

Parts claimed are not consistent to the accident.

Repairer's Estimate (Gross) :S\$ 32,378.20

Revised Amount :S\$ 12,000.00 lump sum

Check Items (Estimated) :S\$ 0.00

Total :S\$ 12,000.00 lump sum

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :\$\$
Pre-Accident Value :\$\$
COE / PARF Rebate :\$\$
Salvage Value :\$\$
Margin for Repair :\$\$

Remarks

()	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage.
		Kindly let us have your authorisation.

() The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(x) Other comments: survey on wp