



TONG LUCK AUTO PTE LTD

160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY, SINGAPORE 575722

Tel: 6250 0088 Fax: 6250 5545

Email: operation@tlauto.com.sg

GST No: 201700521W UEN No: 201700521W

PAGE: 1

M/S : DAIMLER FLEET MANAGEMENT S'PORE PTE LTD

1 GATEWAY DRIVE
#15-08 WESTGATE TOWER
SINGAPORE 608531

TEL : 6849 8118

FAX :

ATTN : ACCOUNTS DEPT

YOUR REF NO : GBH5905R

CLAIM TYPE : THIRD PARTY

TP INS. CO. : ERGO INSURANCE PTE LTD

ACCIDENT DATE : 24/06/2020

TP VEH REG NO : GBH5905R

ESTIMATE

NO : QUOT202006-000045(00)

DATE : 29/06/2020

POLICY NO : 999995580

VEH REG NO : GBF603E

MAKE/MODEL : TOYOTA TOYOTA HIACE VAN
TURBO 5 DR MANUAL

CHASSIS NO : JTFHT02PX00198288

ENGINE NO : 1KD2620818

REG. DATE : 2016

Estimate Repair Cost to Vehicle No : GBF603E

Description	Quantity	Unit Price	Amount
		SS	SS
LIST PRICE			
1 Sliding door - RH	1	1,690.70	1,690.70
2 Sliding door lock - RH	1	298.50	298.50
3 Sliding door inner trimboard - RH	1	303.98	303.98
4 Sliding door trimboard clips - RH	15	5.65	84.75
5 Sliding door outer handle - RH	1	160.70	160.70
6 Rear fender - RH	1	1,763.87	1,763.87
			4,302.50
Less 25%			1,075.61
			3,226.89
LABOUR			
7 To transfer RH damaged door interior mechanism to new door	1	150.00	150.00
8 To check and rectify wiring system	1	80.00	80.00
9 To panel beat and straighten RH front door rear pillar, RH running board panel, to cut and weld RH rear fender, including replacement of parts and align where necessary, to refit and adjust the same	1	1,200.00	1,200.00
10 To putty and spray paint on affected areas	1	1,200.00	1,200.00
11 To apply rust-proofing on replaced and repaired panels	1	120.00	120.00
12 To supply artwork and paste logo on RH body panel	1 (Bill)	1,000.00	1,000.00
			3,750.00

TOTAL **SS 6,976.89**

ADD GST @ 7% 488.38

GRAND TOTAL **SS 7,465.27**

SINGAPORE DOLLAR SEVEN THOUSAND FOUR HUNDRED SIXTY-FIVE AND CENTS TWENTY-SEVEN ONLY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

FOR TONG LUCK AUTO PTE LTD

AUTHORISED SIGNATURE