SMJ 3245 J OK TP/MSIG

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg GST:201001158E RCB NO:201001158E

MSIG INSURANCE (S) PTE LTD (SGX) M/S:

16 RAFFLES QUAY

#24-01 HONG LEONG BUILDING

SINGAPORE 048581

68277660 TEL:

WS Ref:

Claim Type:

Accident Date:

FAX: 62257402

ATTN: Motor Claim Department

Not Nothenthe

TP/MSIG

Third Party 28/06/2020

GBC8812G TP Veh Reg No:

Renny B&pains

Chassis No: Engine No:

Estimate No:

Policy No:

Veh Reg No:

Make/Model:

Date:

SMJ3245J HYUNDAI HYUNDAI AD AVANTE 1.6 GLS (A)

ES2090488/YISHUN

30 Jun 2020

5117708116

KMHD841CMKU865473

G4FGKU094556

28/02/2019 Reg. Date:

Estimate Repair Cost to Vehicle No :SMJ3245J

	Estimate Repair Cost to	U/Price	Quantity	List Price Amount
	Description	U/Price	Quantity	<u>s\$</u> <u>s\$</u>
648				Ry 474 40 —
	List Price	474.40	1 PC	4,1,1,10
/	FRONT BUMPER	25.00	1 PC	25.00
/		164.80	1 PC	CM 164.80 —
/	FRONT BUMPER LH FOG LAMP	33.60	1 PC	Cor 33.60 —
/	FRONT BUMPER LH FOG LAMP SIDE GARNISH	695.80	1 PC	R 695.80 7K
× 5	FRONT BUMPER REINFORCEMENT	119.00	1 PC	N 119.00 XX
\times 6		3.50	6 PCS	Ma 21.00
17	FRONT BUMPER CLIPS	71.70	1 PC	M 71.70
/8		966.80	1 PC	966.80
-9	FRONT LH FENDER	85.70	1 PC	Dir 85.70
/10	FRONT LH FENDER INNER SHIELD	3.50	6 PCS	Ma 21.00 —
- 11	FRONT LH FENDER INNER SHIELD CLIPS	28.00	1 PC	Sen 28.00 2
12	FRONT LH FENDER LAMP	28.00	1 PC	Mil 28.00
13		1,198.80	1 PC	CM 1,198.80 —
14	LH HEADLAMP	30.00	1 PC	n.7 30.00 -
15	LH HEADLAMP LOWER RETAINER	3.50	4 PCS	Ma 14.00 —
16	LH HEADLAMP LOWER RETAINER CLIPS	5.50	4 PCS	Ma 22.00
- 17	LH HEADLAMP LOWER RETAINER RIVETS	115.40	1 PC	CM 115.40 2
	LH HEADLAMP LOWER GARNISH	1,970.70	1 PC	R 1,970.70 —
_ 19	BONNET	179.30	1 PC	20179.30
20	FUSE BOX HOUSING COVER	179.10	1 PC	GCM 179.10
	AIR FILTER RESONATOR	966.80	1 PC	A 966.80 —
	FRONT RH FENDER	85.70	1 PC	CM 85.70 —
/23	FRONT RH FENDER INNER SHIELD FRONT RH FENDER INNER SHIELD CLIPS	3.50	6 PCS	14 21.00 <u> </u>
_ 24		28.00	1 PC	LA 28.00 —
	FRONT RH FENDER LAMP FRONT RH FENDER TRIANGLE GARNISH	18.00	1 PC	miy 18.00
		164.80	1 PC	year 164.80 7-
/ 27	FRONT BUMPER RH FOG LAMP FRONT BUMPER RH FOG LAMP GARNISH	47.00	1 SET	Cos 47.00 7
	RH HEADLAMP	1,198.80	1 PC	Gr 1,198.80

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg GST:201001158E RCB NO:201001158E

M/S: MSIG INSURANCE (S) PTE LTD (SGX)

16 RAFFLES QUAY

#24-01 HONG LEONG BUILDING

SINGAPORE 048581

TEL: 68277660

ATTN: Motor Claim Department

FAX: 62257402

Make/Model:

Chassis No:

Date:

AD AVANTE 1.6 GLS (A)

HYUNDAI HYUNDAI

ES2090488/YISHUN

KMHD841CMKU865473

Engine No:

Estimate No:

Policy No:

Veh Reg No:

G4FGKU094556

Reg. Date:

28/02/2019

30 Jun 2020

5117708116

SMJ3245J

Accident Date: TP Veh Reg No:

WS Ref:

Claim Type:

28/06/2020 **GBC8812G**

TP/MSIG

Third Party

Estimate Repair Cost to Vehicle No :SMJ3245J

	Estimate Repair Cost to ver		Quantity	List Price	Amount
	Description	U/Price	Quantity	SS	<u>S\$</u>
/ **	DILLUTADI AMB LOWED BEAM RETAINER	25.00	1 PC	Sn 25.00 7	X
, ,	RH HEADLAMP LOWER BEAM CLUS	3.50	4 PCS	Ma 14.00 7	
_ 31	RH HEADLAMP LOWER BEAM CLIPS	5.50	4 PCS	Ma 22.00 -	
_ 32	RH HEADLAMP LOWER BEAM RIVETS	115.40	1 PC	cm 115.40 7	
33	RH HEADLAMP LOWER GARNISH	696.30	1 PC	nd 696.30 -	-
34	FRONT RH SPORT RIM	372.50	1 PC	372.50 7	/
_ 35	FRONT RH SHOCK ABSORBER	363.60	1 PC	B1 363.60 7	
_ 36	FRONT RH KNUCKLE ARM	363.60	1 PC	363.60	X
\times 37	FRONT RH LOWER ARM	452.80	1 PC	Ne 452.80 7	
38	FRONT RH WHEEL BEARING	1,904.70	1 PC	1,904.70	
39	FRONT LH DOOR	36.00	1 PC	M 36.00 -	
 40	FRONT LH DOOR STICKER	1,904.70	1 PC	R ₁ 1,904.70 -	
41	FRONT RH DOOR	36.00	1 SET	May 36.00 -	
-42	FRONT RH DOOR FRAME STICKER	696.30	1 PC	Mad 696.30 -	
-43	FRONT LH SPORT RIM	372.50	1 PC	Rg 372.50 -	_
44	FRONT LH SHOCK ABSORBER	363.60	1 PC	R 363.60 —	_
45	FRONT LH KNUCKLE ARM	452.80	1 PC	Mer 452.80 -	_
46	FRONT LH WHEEL BEARING	936.70	1 PC	R 936.70 €	
47	FRONT LH DRIVE SHAFT	133.80	1 PC	Ly 133.80 -	
48	ENGINE FRT UNDER COVER	74.90	1 PC	Ry 74.90 -	
	FRONT LH LINKAGE	1,188.70	1 PC	S→ 1,188.70 🗶	X
X 50	ENGINE REAR CROSS MEMBER	116.40	1 PC	By 116.40 7	'
51	FRONT LH SHOCK ABSORBER TOP MOUNTING	28.00	2 PCS	DIT 56.00 7	
	FRONT SUPPORT PANEL SIDE EXTENSION RETAINERS	1,064.90	1 PC	1,064.90 X	.大
₹ 53	STEERING RACK & PINION	,	-	20,737.40	
			Less 20%	4,147.48	16,589.92
	Labour				,
	Labour	100.00	1 LA	100.00	
54	TOWING	100.00	1 LA	100.00	
	REMOVE AND REFIX AIRCON,CHECK,VACUUM & REFILL GAS				

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg GST:201001158E RCB NO:201001158E

M/S: MSIG INSURANCE (S) PTE LTD (SGX)

TP/MSIG

Third Party

28/06/2020

16 RAFFLES QUAY

#24-01 HONG LEONG BUILDING

SINGAPORE 048581

68277660

TEL:

WS Ref:

Claim Type:

Accident Date:

TP Veh Reg No:

ATTN: Motor Claim Department

FAX: 62257402

Estimate No: Date:

Policy No:

ES2090488/YISHUN

30 Jun 2020 5117708116

Veh Reg No: SMJ3245J

Make/Model: HYUNDAI HYUNDAI

Chassis No:

AD AVANTE 1.6 GLS (A) KMHD841CMKU865473

Engine No:

G4FGKU094556

Reg. Date:

28/02/2019

GBC8812G

Estimate Repair Cost to Vehicle No: SMJ3245J

	Description Estimate Repair Cost to Vehi	- Manager			
		U/Price	Quantity	List Price	Amount
56	REMOVE & REFIX FRT BOTH UNDER CARRIAGE, DRIVE SHAFT, CHECK STEERING & ENGINE CROSS MEMBER	380.00	1 LA	<u>\$\$</u> 380.00	32d S\$
57	ASSY, HEADLAMPS, SUPPORT PANEL, FRT FENDERS, FRT RH & LH DOORS & ATTACHMENTS YNOCK & REPAIR TO	1,600.00	1 LA	1,600.00	1300
	WHEEL HOUSINGS, REAR RH DOOR, REAR RH FENDER, REAR BUMPER & REALIGN THE SAME				
58	REMOVE & REFIX FRT BOTH DOOR GLASS & CHECK POWER MIRROR	120.00	1 LA	120.00	_
59	PUTTY & RESPRAY ON REAR BUMPER, REAR RH FENDER, FRT & REAR RH DOORS, FRT BUMPER, FRT BOTH FENDERS, BONNET, FRT LH DOOR & ALL AFFECTED AREAS	1,800.00	1 LA	1,800.00	16001
60	TO CHECK REAR UNDER CARRIAGE AND CONDUCT COMPUTERIZED WHEEL ALIGNMENT	60.00	1 LA	60.00	~
61	REMOVE & REFIX FRT BOTH SPORT RIM & CONDUCT COMPUTERIZED BALANCING	40.00	1 LA	40.00	V
62	RUSTPROOFING	90.00	1 LA	90.00	_
				4,290.00	4,290.00

Parts # 17282.40

Hall Supp # 18,070.90

A 18,070.90

A 18,070.90

A 14,458

A 14,458

Trejudice basis

Total S\$ 20,879.92 Add GST @ 7% 1,461.59 Total Amount Payable S\$ 22,341.51

21,512.32 For Cheng Hoe Motor Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following: . To resurvey before/after spray painting

To display damaged part(s) during resurv

Parts prices are subject to confirmation

Third party survey is on a "Without Prejudice" basis

No illegal modification(s) is allowed

 Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Comp

Acknowledged by Repairer

Signature:

Date:

AUTHORISED SIGNATURE

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg GST:201001158E RCB NO:201001158E

SMJ3245J Supp 1

M/S:

MSIG INSURANCE (S) PTE LTD (SGX)

16 RAFFLES QUAY

#24-01 HONG LEONG BUILDING

SINGAPORE 048581

TEL:

WS Ref:

68277660

FAX: 62257402

ATTN: Motor Claim Department

Claim Type: Accident Date:

Third Party 28/06/2020

TP/MSIG

TP Veh Reg No: **GBC8812G** **Estimate No:**

ES2090488/YISHUN

Date:

02 Jul 2020

Policy No:

5117708116

Veh Reg No:

SMJ3245J

Make/Model:

HYUNDAI HYUNDAI

AD AVANTE 1.6 GLS (A)

KMHD841CMKU865473

S\$ 676.67

Chassis No: Engine No:

G4FGKU094556

Reg. Date:

28/02/2019

Estimate Renair Cost to Vehicle No . SM 132451

	Description	U/Price	Quantity	List Price		Amount
					<u>S\$</u>	<u>SS</u>
		Supplementary 1				
	List Price			an		
1	TAILLAMP LH	434.90	1 PC	001	434.90	
2	FRONT LH LOWER ARM	355.60	1 PC	BI	434.90 355.60	
					790.50	
			Less 20%		158.10	632.40
				Tota	l	S\$ 632.40
	LKK Auto Consultants hence notify		G	ST Amoun	t	S\$ 44.27
	the state of the s					

the Repairer of the following:

- . To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- · No illegal modification(s) is allowed
- . Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

For Cheng Hoe Motor Pte Ltd

Total Amount Payable

AUTHORISED SIGNATURE