

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

(Sat)
Date: 27.06.2020
Time: 09:16:42
Page: 1

Right Side
(Ls)

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305407339
REGN NO : SHC8991B
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : I-40
DATE OF REGN : 19.05.2016
DATE/TIME IN : 26.06.2020 14:20
ACCIDENT DATE : 26.06.2020

0930

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0579-G	REAR BUMPER	1	1,106.00	20.00	884.80	de ✓
0002 04-01-0103-0738-G	REAR BUMPER UNDER COVER	1	228.00	20.00	182.40	Rx ✓
0003 04-01-0101-0111-G	REAR BUMPER CLIPS	10 L	22.00	20.00	17.60	all ✓
0004 09-01-9999-0068-A	REVERSE SENSOR	1	135.70		135.70	7x ✓
0005 04-01-0103-1150-A	REAR BUMPER MAT	1	50.00		50.00	all ✓

SUB-TOTAL : 1,270.50

JOB NATURE

0000 PB	PANEL BEATING
0001 SP	SPRAYPAINT CHARGE
0002 L	R/T REVERSE SENSOR

300.00 280.
250.00 200
120.00 30.

SUB-TOTAL : 670.00

952.40
510
1482.40
510
4581.50
2 days #

Taplin 97495749
-wp
L/S Repair after repair
21/6/20 0320pm
02 days
Taplin @ 11/6/2020

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: