

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

(Csat)

Date: 27.06.2020

Time: 09:16:42

Page: 1

Aigrid  
(45)

COMPANY : THIRD PARTY'S CLAIMS (CAS)  
 CUSTOMER: 7010045  
 ADDRESS : COMFORT TRANSPORTATION PTE LTD  
 383 SIN MING DRIVE  
 SINGAPORE SINGAPORE 575717  
 65508755

JOB NO : 305407339  
 REGN NO : SHC8991B  
 MILEAGE : 0000000000  
 MAKE : HYUNDAI  
 MODEL : I-40  
 DATE OF REGN : 19.05.2016  
 DATE/TIME IN : 26.06.2020 14:20  
 ACCIDENT DATE : 26.06.2020

0930

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

## PART REQUISITION

| QTY  | IND               | UNIT-PRICE              | DISC% | AMOUNT                     |
|------|-------------------|-------------------------|-------|----------------------------|
| 0001 | 04-01-0103-0579-G | REAR BUMPER             | 1     | 1,106.00 20.00 884.80 de ✓ |
| 0002 | 04-01-0103-0738-G | REAR BUMPER UNDER COVER | 1     | 228.00 20.00 182.40 RX ✓   |
| 0003 | 04-01-0101-0111-G | REAR BUMPER CLIPS       | 10 L  | 22.00 20.00 17.60 al ✓     |
| 0004 | 09-01-9999-0068-A | REVERSE SENSOR          | 1     | 135.70 135.70 ?            |
| 0005 | 04-01-0103-1150-A | REAR BUMPER MAT         | 1     | 50.00 - 50.00 al ✓         |

SUB-TOTAL : 1,270.50

## JOB NATURE

|         |                    |        |      |
|---------|--------------------|--------|------|
| 0000 PB | PANEL BEATING      | 300.00 | 280. |
| 0001 SP | SPRAYPAINT CHARGE  | 250.00 | 200  |
| 0002 L  | R/I REVERSE SENSOR | 120.00 | 30.  |

SUB-TOTAL : 670.00

Taplin 97495749  
 -wp  
 1/3 Repair after repair  
 21/6/20 0320pm  
 02 days  
 Taplin @ Henderson.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

REPAIR ESTIMATE

CSat)

Date: 27.06.2020

Time: 09:16:42

Page: 2

12 TS

|               |   |                  |
|---------------|---|------------------|
| JOB NO        | : | 305407339        |
| REGN NO       | : | SHC8991B         |
| MILEAGE       | : | 0000000000       |
| MAKE          | : | HYUNDAI          |
| MODEL         | : | I-40             |
| DATE OF REGN  | : | 19.05.2016       |
| DATE/TIME IN  | : | 26.06.2020 14:20 |
| ACCIDENT DATE | : | 26.06.2020       |

[illegible]

TOTAL : 1,940.50

AUTHORISED : YES / NO

MVA NAME & SIGNATURE  
DATE :

\_\_\_\_\_  
SURVEYOR NAME & SIGNATURE  
DATE :