

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

WIP : 39444

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0451/2020/NS
Date : 29-Jun-20

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured veh no : SLC 2761 R

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr Tan Eng Hock
Address : 21 Elias Road
#07-02
Singapore 519929
Telephone : (HP) +65 97346519
Type of Claim : Third Party Claims
Policy No. : 1900133359
Vehicle No : **SMN 905 L**
Model Code : Audi A3 Sedan 1.0 TFSI 8V
Model / Year : 24/7/2019
Engine No : CHZ C27357
Chassis No : WAUZZZ8V0K1024973
Mileage : -
Date In : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 29-Jun-20
Place of Accident : PIE Towards City

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel: 6366 2329 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle. SMN 905 L

S/n	Nature of Jobs	Estimated Charges	Surveyor's Recommendations
1	To remove and transfer rear parking aid. Check function and renew according to damage.	S/N \$ 280.00	✓
2	To dismantle and renew rear bumper. To repair rear lid. Re-organise rear crash management components. Reinstall all parts removed.	\$ 1,400.00	500
3	To respray rear bumper and rear lid.	\$ 2,000.00	550
4	To carry out diagnostic check.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 3,872.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel - 6366 2323 Fax 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMN 905 L

S/N	Parts Description	Damaged Parts & Prices		Remarks
		S/Nett		
1	REAR BUMPER <i>Deland</i>	\$	1,851.00	✓
2	REAR BUMPER STICKY PAD <i>ne</i>	4 \$	22.00	✓
3	REAR BUMPER FIXING PARTS <i>ne ne</i>	\$	182.00	+
4	REAR BUMPER GUIDE SECTION - LH / RH <i>ne ne</i>	2 \$	30.00	✓
5	REAR BUMPER LOCKING MECHANISM	2 \$	55.00	+
6	REAR BUMPER SPOILER - LH <i>Ct</i>	\$	223.00	✓
7	REAR LIGHT REFLECTOR - LH / RH <i>ne ne</i>	2 \$	78.00	+
8	REAR BUMPER SIDE REINFORCEMENT BEAM <i>not ne</i>	\$	538.00	+
9	REAR BUMPER BRACKET - LH <i>ne ne</i>	\$	26.00	✓
10	REAR BUMPER BRACKET - RH <i>ne ne</i>	\$	27.00	✓
11	REAR PARKING AID SENSOR - INNER / OUTER <i>ne ne</i>	2	TBC	+
12	REAR PARKING AID SEAL RING <i>ne ne</i>	4 \$	14.00	+
13	AUDI EMBLEM <i>ne ne</i>	\$	117.00	+
14	A3 INSCRIPTION <i>ne ne</i>	\$	90.00	+
15	PACKING ADHESIVE	\$	18.00	+
16	SUNDRIES <i>?</i>	\$	200.00	?
TOTAL SPARE PARTS		:	\$ 3,471.00	
TOTAL LABOUR CHARGES		:	\$ 3,872.00	
GRAND TOTAL		:	\$ 7,343.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adnan Ling
Surveyed Date : 29/06/20
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 03 days

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel: 6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant