

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/III20006789/UGA3Q2**Date:** 14/09/2020REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant</b>		
<b>Vehicle No :</b> SMP6302B	<b>Insured Vehicle No :</b>	SHA1423G
Date of Loss: 26/06/2020	Nature of Claim: TP	Claim No: MCT20060309

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SMP6302B</b>		
Make & Model:	HONDA CIVIC, 1.6 VTI CVT (A)	Engine No:	R16B25511163
Reg. Date:	03/10/2019 (Man. Year: 2019)	Chassis No:	MRHFC5650KT001048
Colour:	Blue	Odometer:	8646 km
Engine Capacity:	1597 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/55 R16	Rear Tyre Size:	215/55 R16
Front Left Side:	Hankook 7 mm	Rear Left Side:	Hankook 7 mm
Front Right Side:	Hankook 7 mm	Rear Right Side:	Hankook 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	769.53	494.97	274.56	35.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,930.00	1,320.00	1,610.00	54.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>3,699.53</b>	<b>1,814.97</b>	<b>1,884.56</b>	<b>50.94</b>
<b>+ GST 7.00/7.00% (S\$)</b>	258.97	127.05	131.92	50.94
<b>Nett Amount (S\$)</b>	<b>3,958.50</b>	<b>1,942.02</b>	<b>2,016.48</b>	<b>50.94</b>
<b>+ Car Rental (3.0 x S\$100.00/day + 7.00% GST) (S\$)</b>		321.00		
	<b>Nett Liability (S\$)</b>	<b>2,263.02</b>		

INSPECTION

Date of Assignment:	29/06/2020		
Date Inspected:	06/07/2020	Inspected At:	Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4 Singapore 408610
Estimated Period of Repair:	3.0 days		

**Adjuster:** MARCUS CHUA**Manager:** Chong Pui Lin

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 01 Sep 2020)
<b>Parts:</b> 143	HONDA CIVIC 1.6 VTI CVT (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMP6302B)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*FACE ASSY ,RR. BUMPER	Dented / Deformed	462.90 FS	*462.90 FS	
2	1		*BEAM ,COMPRR.BUMPER	Serviceable	135.00 FS	*- FS	
3	1		*CLIP .BUMPER	Necessary	12.07 FS	*12.07 FS	
4	1		*SPACERR.RR.BUMPER SIDE	Not Necessary	8.62 FS	*- FS	
5	1		*SPACERL.RR.BUMPER SIDE	Not Necessary	8.62 FS	*- FS	
6	1		*GARNISH ASSY ,RR.BUMPER LOWER	Not Necessary	92.32 FS	*- FS	
7	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS	
					<b>Total Parts (\$)</b>	<b>769.53</b>	<b>494.97</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	INSPECT RR LIGHTING MECHANISMS ,PERFORM WATER	New	150.00	0.00
2	REMOVE & INSTALLREVERSE SENSORS	New	180.00	150.00
3	STRAIGHTEN ALIGN RR PANEL & RENEW DAMAGE PARTS	New	1,500.00	650.00
4	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS	New	1,100.00	520.00
			<b>Gross Labour Cost (\$\$)</b>	<b>1,320.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >