





**KAH MOTOR CO. SDN. BHD.**  
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

# QUOTATION

GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

<b>Customer</b>	: INDIA INTERNATIONAL INSURANCE PTE 64 CECIL STREET #04-00 & #05-00 IOB BUILDING SINGAPORE 049711	<b>Document No.</b>	: SQT20001961	<b>Page</b>	1
<b>Registration No</b>	: SMP6302B	<b>Date</b>	: 26. Jun 2020	<b>Customer No.</b>	: WZ1007
<b>Chassis No</b>	: MRHFC5650KT001048	<b>Svc Advisor</b>	: YOU PO SOON	<b>Engine No</b>	: R16B25511163
<b>Model</b>	: CIVIC 1.6 VTI YM2019	<b>Date   Time</b>	: 26. Jun 2020 5:26:46 PM	<b>Surveyor Name</b>	:
<b>Owner's Name</b>	: YONG KEAN SOON DARRYL	<b>Survey Date</b>	:	<b>Authorisation Date</b>	:
<b>Ins Policy No.</b>	:				
<b>Date of Accident</b>	: 26/6/2020				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Includ GST
	TP DIRECT SETTLEMENT (J/NO: ) OWNER:YONG KEAN SOON OWNER INSURER: TOKIO MARINE INSURANCE ACC DATE: 26/6/2020 SURVEYED BY: DATE: REF NO: TP INSURER: INDIA INSURANCE TP VEH: SHA1423G						
71500-TEC-Q00ZZ	FACE ASSY,RR.BUMPER	1	617.20	25	462.90	32.40	495.30
71530-TEA-T00ZZ	BEAM COMPRR.BUMPER	1	180.00	X 25	135.00	9.45	144.45
91505-TM8-003	CLIP,BUMPER	7	2.30	25	12.07	0.84	12.91
71593-TEA-T01	SPACERR.RR.BUMPER SIDE	1	11.50	X 25	8.62	0.60	9.22
71598-TEA-T01	SPACERL.RR.BUMPER SIDE	1	11.50	X 25	8.62	0.60	9.22
71510-TEA-T50	GARNISH ASSY,RR.BUMPER LOWER	1	123.10	X 25	92.32	6.46	98.78
	<b>Sum Item</b>				<b>719.53</b>	<b>50.35</b>	<b>769.88</b>
BOSUN	SUNDRIES	1	50.00	20	50.00	3.50	53.50
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	150.00	X	150.00	10.50	160.50
BA02R	REMOVE & INSTALLREVERSE SENSORS-4 PCS (N)	1	180.00	150	180.00	12.60	192.60
BKRP02S	STRAIGHTEN ALIGN RR PANEL & RENEW DAMAGE PARTS.	1	1500.00	650	1500.00	105.00	1605.00
BP01R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (2P)	1	1100.00	520	1100.00	77.00	1177.00
	<b>Sum Labor</b>				<b>2980.00</b>	<b>208.60</b>	<b>3,188.60</b>

Survey By: Marcus Hark  
Date & Time: 6/7/20 # 1814.97

**Total Amount** 3,699.53 258.95 3,958.48

Printed on 26/6/2020 5:32:54 PM  
This is a computer generated invoice. No signature is required.  
Part prices are subjected to change without notice.  
The above estimated cost of repair do not include any unforeseen damages.  
GST Amount is calculated from individual line(s).  
An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.  
However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.



**KAH MOTOR CO. SDN. BHD.**  
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

# QUOTATION

GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

**Customer** : INDIA INTERNATIONAL INSURANCE PTE  
64 CECIL STREET  
#04-00 & #05-00 IOB BUILDING  
SINGAPORE 049711

**Registration No** : SMP6302B

**Chassis No** : MRHFC5650KT001048

**Model** : CIVIC 1.6 VTI YM2019

**Owner's Name** : YONG KEAN SOON DARRYL

**Ins Policy No.** :

**Date of Accident** : 26/6/2020

**Document No.** : SQT20001961 Page 2

**Date** : 26. Jun 2020

**Customer No.** : WZ1007

**Svc Advisor** : YOU PO SOON

**Engine No** : R16B25511163

**Date | Time** : 26. Jun 2020 5:26:46 PM

**Surveyor Name** :

**Survey Date** :

**Authorisation Date** :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
Excess							
<b>Total (Inclusive of GST)</b>							<b>3,958.48</b>

Status *not authorized*

Signature *Take photo before repairing.  
3 days.*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Printed on 26/6/2020 5:32:54 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

15/8/2020

page 1/1

**HONDA** Attn: Marcus

# SERVICE PRE-INVOICE

**KAH MOTOR CO. SDN. BHD.** WD: 3 Day  
(A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022  
255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5480

<b>Customer:</b>	CU0115225 / INDIA	<b>Document No:</b>	SVO20037596
<b>Chassis No:</b>	MRHFC5650KT001048	<b>Printed By:</b>	PSYOU
<b>License No:</b>	SMP6302B	<b>Order Date:</b>	3. August 2020
<b>Mileage:</b>	9597	<b>Order Time:</b>	8:22:44 AM
<b>Engine No:</b>	R16B25511163	<b>Service Advisor:</b>	YOU PO SOON

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Incl GST
	TP DIRECT SETTLEMENT (J/NO: 74940 ) OWNER:YONG KEAN SOON OWNER INSURER: TOKIO MARINE INSURANCE ACC DATE: 28/6/2020 SURVEYED BY: MARCUS CHUA DATE: REF NO: TP INSURER: INDIA INSURANCE TP VEH: SHA1423G						
71500-TEC-Q00ZZ	FACE ASSY,RR,BUMPER	1	617.20	25	462.90	32.40	495.30
91505-TM8-003	CLIP,BUMPER	7	2.30	25	12.07	0.84	12.91
	<b>SUM PARTS:</b>				<b>474.97</b>	<b>33.24</b>	<b>508.21</b>
BOSUN	0760 SUNDRIES	1	20.00		20.00	1.40	21.40
BA02R	EXT-YJ REMOVE & INSTALL REVERSE SENSORS-4 PCS (N)	1	150.00		150.00	10.50	160.50
BKRP02S	EXT-YJ STRAIGHTEN ALIGN RR PANEL & RENEW DAMAGE PARTS.	1	650.00		650.00	45.50	695.50
BP01R	EXT-YBH SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(1P)	1	520.00		520.00	36.40	556.40
	<b>SUM LABOUR:</b>				<b>1,340.00</b>	<b>93.80</b>	<b>1,433.80</b>
	<b>TOTAL SGD</b>				<b>1,814.97</b>	<b>127.04</b>	<b>1,942.01</b>
	<b>Total Payable (SGD)</b>						<b>1,942.01</b>

GST Amount is calculated from individual line(s)