

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

29 JUN 2020

ESTIMATE

Estimate No. : b1 55364 Page No. : 1 of 5
Date Estimated : 29/06/2020
Prepared By : Foong Shiuh Jye

- ESTIMATE REPAIR FOR -
Leong Lai Fun Liza
7 Lily Avenue
Singapore 277782

- ACCOUNT - 219
India Int'L Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
FZ821P	WBAJG120403G76761	29/10/2018	X1 sDrive18i	0

DESCRIPTION	VALUE
To replace bumper rear cover, side sill trim and attachments	1700 3,400.00
To repair rear left side panel	
To spray paint bumper rear cover, rear left side panel and wheelarch trim	1730 2,292.00
To check steering geometry and conduct wheel alignment according to BMW specification (1X)	451 531.00
To replace wheel rim left rear including balancing. (1x).	80 94.00
To supply tyre.	X 500.00
To check electrical wiring systems and lightings at the rear section for proper function.	150 177.00
Sundries.	? 80.00

Total Labour 1: 7,074.00

DESCRIPTION	QTY	PRIC	VALUE
ALLOY RIM 7.5X17 V SPK 560 <i>SCA</i>	1	814.00	814.00
REAR LH BUMPER MOUNT ?	1	161.40	161.40
RR BUMPER LH CORNER MOUNTING ?	1	142.65	142.65
REAR BUMPER PANEL PRIMED <i>SCA</i>	1	903.40	903.40
REAR BUMPER MIDDLE TRIM PANEL (PDC) <i>SCA</i>	1	265.65	265.65
FRT LH MOULDING ROCKER PANEL X	1	79.95	79.95
REAR LH MOULDING ROCKER PANEL X	1	64.55	64.55
LH SIDE SKIRT TRIM (BASIS) X	1	235.65	235.65
REAR LH WHEELARCH TRIM <i>SCA</i>	1	151.80	151.80

Total Parts : 2,819.05

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorroad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 55364
Date Estimated : 29/06/2020
Prepared By : Foong Shiuh Jye

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFZ821P	WBAJG120403G76761	29/10/2018	X1 sDrive18i	0

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 20/07/2020 @ 1210 Excess S\$ _____

Surveyor's Name Rashid Sign _____

Surveyor's Tel 90010088 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No _____

Surveyor's E-mail _____

No. of Working Days Recommend 5 days

Regy same print

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:



Labour 1	:	7,074.00
Parts	:	2,819.05
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	692.51
Grand Total	:	10,585.56

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **