

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20006797/APA3Q2
Date: 12/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No: 2070012875	
Claimant Vehicle No : SKV4659C	Insured Vehicle No : SFP6084M	
Date of Loss: 29/06/2020	Nature of Claim: TP	Claim No: 7569245629SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKV4659C		
Make & Model: HONDA CITY, 1.5 SV CVT (A)	Engine No: L15Z12712417	
Reg. Date: 18/09/2015 (Man. Year: 2015)	Chassis No: MRHGM6660GP000231	
Colour: Grey	Odometer: 133082 km	
Engine Capacity: 1497 cc		
Market Value/New Car Price: N/A		
Sum Insured (S\$): Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable): Yes	Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes	Engine Modification: No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/55 R16	Rear Tyre Size: 185/55 R16	
Front Left Side: Falken 6 mm	Rear Left Side: Falken 6 mm	
Front Right Side: Falken 6 mm	Rear Right Side: Falken 6 mm	

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,501.92	1,687.12	814.80	32.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,430.00	1,840.00	590.00	24.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,931.92	3,527.12	1,404.80	28.48
Approved Total (Overridden) (S\$)		2,800.00		
(S\$)	4,931.92	2,800.00	2,131.92	43.23
+ GST 7.00/7.00% (S\$)	345.23	196.00	149.23	43.23
Nett Amount (S\$)	5,277.15	2,996.00	2,281.15	43.23
+ Loss of Use (7.0 x S\$60.00/day) (S\$)		420.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,418.00		
Global Sum Settlement (S\$)		3,400.00		

INSPECTION

Date of Assignment: 29/06/2020		
Date Inspected: 29/06/2020	Inspected At:	Kang Car Repairers Pte Ltd (HQ) No 1 Kaki Bukit Ave 6, #02-06 AutoBay@Kaki Bukit Singapore 417883
Estimated Period of Repair: 6.0 days		

Adjuster: ADRIAN LING**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	483.70 FL	*483.70 FL
2	2		*REAR BUMPER SIDE RETAINER	Necessary	63.20 FL	*63.20 FL
3	4		*REVERSE SENSOR	Damaged (2 PCS ONLY)	758.40 FL	*379.20 FL
4	1		*REAR PANEL	Dented	380.90 FL	*380.90 FL
5	1		*REAR PANEL TRIM	Cracked	91.40 FL	*91.40 FL
6	1		*BOOT LID	Buckled	564.10 FL	*564.10 FL
7	1		*BOOT LID RUBBER	Not Necessary	97.70 FL	*- FL
8	1		*BOOTLID INNER LOCK	Not Necessary	109.40 FL	*- FL
9	1		*BOOTLID INNER TRIM	Not Necessary	124.60 FL	*- FL
10	1		*BOOT LID LAMP RH	Not Necessary	245.10 FL	*- FL
11	1		*BOOTLID CITY EMBLEM	Necessary	29.40 FL	*29.40 FL
12	1		*BOOTLID H EMBLEM	Necessary	25.60 FL	*25.60 FL
13	1		*BOOT LID I-VTEC EMBLEM	Necessary	28.90 FL	*28.90 FL
14	1		*SET REAR BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
15	1		*SET REAR PANEL TRIM CLIPS	Necessary	40.00 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,102.40	2,096.40
- List Item Discount on L Items 20.00/20.00% (\$\$)	600.48	409.28
Total Parts (\$\$)	2,501.92	1,687.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	30.00
2	TO SPRAY UNDERSEAL	New	100.00	60.00
3	TO REMOVE AND REFIT REVERSE SENSOR	New	100.00	50.00
4	TO REMOVE AND REFIT REVERSE CAMERA	New	100.00	50.00
5	TO REMOVE AND REFIT INNER TRIM	New	80.00	50.00
6	(REAR) TO SPRAY PAINTING	New	1,000.00	800.00
7	TO REMOVE AND REPLACE THE DAMAGED PARTS,KNOCK OUT ACCIDENT DENTED PORTIONS ,AND FOR CUTTING /WELDING WORKS	New	1,000.00	800.00
Gross Labour Cost (\$\$)			2,430.00	1,840.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >