

CC6/AIG20006797/Aka3

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
 TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
 GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY #07-16
 AIG BUILDING, SINGAPORE 079120
TEL: 64193000 **FAX:** 68357416
ATTN: Motor Claim Department

Estimate No: EST2000118
Date: 29 Jun 2020
Veh Reg No: SKV4659C
Make/Model: HONDA CITY 1.5 SV CVT
Chasis No: MRHGM6660GP000231
Reg. Date: 18/09/2015
Your Ref No: SFP6084M

Claim Type: Third Party
Accident Date: 29/06/2020
TP Veh Reg No: SFP6084M

1chanchuan

Estimate Repair Cost to Vehicle No :SKV4659C

Quantity	Description	List Price	Amount
		<u>SS</u>	<u>SS</u>
List Price			
1	1 PC REAR BUMPER <i>2 hand</i>	483.70 ✓	
2	2 PCS REAR BUMPER SIDE RETAINER <i>new</i>	63.20 ✓	
3	4 PCS REVERSE SENSORS <i>2 pieces damaged</i>	758.40 ✓	2.379.20
4	1 PC REAR PANEL <i>dented</i>	380.90 ✓	
5	1 PC REAR PANEL TRIM <i>cracked</i>	91.40 ✓	
6	1 PC BOOT LID <i>Buckled</i>	564.10 ✓	
7	1 PC BOOT LID RUBBER <i>new</i>	97.70 ✓	
8	1 PC BOOTLID INNER LOCK <i>new</i>	109.40 ✓	
9	1 PC BOOTLID INNER TRIM <i>new</i>	124.60 ✓	
10	1 PC BOOT LID LAMP RH <i>new</i>	245.10 ✓	
11	1 PC BOOTLID "CITY" EMBLEM <i>2</i>	29.40 ✓	
12	1 PC BOOTLID "H" EMBLEM <i>new</i>	25.60 ✓	
13	1 PC BOOT LID "I-VTEC" EMBLEM	28.90 ✓	
		3,002.40	
	Less 20%	600.48	2,401.92
Special Net			
14	1 SET REAR BUMPER CLIPS <i>new</i>	60.00 ✓	30
15	1 SET REAR PANEL TRIM CLIPS <i>new</i>	40.00 ✓	20
		100.00	100.00
Labour			
16	1 TO CHECK WIRING	50.00 ✓	30
17	1 TO SPRAY UNDERSEAL	100.00 ✓	60
18	1 TO REMOVE AND REFIT REVERSE SENSOR	100.00 ✓	50
19	1 TO REMOVE AND REFIT REVERSE CAMERA	100.00 ✓	50
20	1 TO REMOVE AND REFIT INNER TRIM	80.00 ✓	50
21	1 (REAR) TO SPRAY PAINTING	1,000.00 ✓	800
22	1 TO REMOVE AND REPLACE THE DAMAGED PARTS, KNOCK OUT ACCIDENT DENTED PORTIONS, AND FOR CUTTING/WELDING WORKS.	1,000.00 ✓	800

2046.40

1637.12

50

1840

Kang Car Repairers Pte Ltd

1 Kaki Bukit Ave 6, #02-06 Autobay@ Kaki Bukit Singapore 417883
TEL: 6747 7636 FAX: 6748 5071 Email: kangcar@singnet.com.sg
GST:201300201N

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY #07-16
AIG BUILDING, SINGAPORE 079120
TEL: 64193000 **FAX:** 68357416
ATTN: Motor Claim Department

Claim Type: Third Party
Accident Date: 29/06/2020
TP Veh Reg No: SFP6084M

Estimate No: EST2000118
Date: 29 Jun 2020
Veh Reg No: SKV4659C
Make/Model: HONDA CITY 1.5 SV CVT
Chasis No: MRHGM6660GP000231
Reg. Date: 18/09/2015
Your Ref No: SFP6084M

Estimate Repair Cost to Vehicle No :SKV4659C

Quantity	Description	List Price	Amount
		SS	SS
		2.430.00	2.430.00
Total			S\$ 4,931.92
Add GST @ 7%			345.23
Total Amount Payable			S\$ 5,277.15

TOTAL: SINGAPORE DOLLAR FIVE THOUSAND TWO HUNDRED SEVENTY SEVEN AND CENTS FIFTEEN ONLY

This is only an estimate based on our preliminary inspection and does not cover additional parts, labour time which may be required after work has begun.

For Kang Car Repairers Pte Ltd



AUTHORISED SIGNATURE

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2.8K

Adrian Ly
1/2 29/06/20

06 Days

total 3527.12

c/s 2.8K