

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20006799/KDA3Q2**Date:** 28/08/2020REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800053474
Claimant
Vehicle No : SLX2278J **Insured Vehicle No :** SCW230X
Date of Loss: 25/06/2020 Nature of Claim: TP Claim No: 8339014095SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLX2278J**
Make & Model: MERCEDES-BENZ E200, 2.0 SEDAN (R17) (A) Engine No: 27492030193850
Reg. Date: 24/06/2014 (Man. Year: 2014) Chassis No: WDD2120342B024227
Colour: Metallic Brown Odometer: 111960 km
Engine Capacity: 1991 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 245/45 R17 Rear Tyre Size: 245/45 R17
Front Left Side: General 9 mm Rear Left Side: General 9 mm
Front Right Side: General 9 mm Rear Right Side: General 9 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|-------------------|-------------------|-------------------|---------------|
| Parts | 5,337.00 | 1,741.50 | 3,595.50 | 67.37 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 1,170.00 | 570.00 | 600.00 | 51.28 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 6,507.00 | 2,311.50 | 4,195.50 | 64.48 |
| Approved Total (Overridden) (S\$) | | 1,850.00 | | |
| Nett Amount (S\$) | 6,507.00 | 1,850.00 | 4,657.00 | 71.57 |
| Global Sum Settlement (S\$) | | 0.00 | | |

INSPECTION

Date of Assignment: 30/06/2020
Date Inspected: 06/07/2020 Inspected At: Hwa Seng Spray Painting Co (160 SIN MING)
160 SIN MING DRIVE, #05-11 SIN MING AUTOCITY
Singapore 575722
Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG**Manager:** CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount | |
|-----|-----|----------|------------------------------|---------------|--|-----------------|-----------------|
| 1 | 1 | | *FRONT BUMPER | Buckled / Cut | 1,650.00 FL | *1,650.00 FL | |
| 2 | 1 | | *FRONT BUMPER RIGHT RETAINER | Serviceable | 95.00 FL | *- FL | |
| 3 | 1 | | *O/S/F SENSOR | Scratched | 285.00 FL | *285.00 FL | |
| 4 | 1 | | *RIGHT HEADLAMP | Serviceable | 3,900.00 FL | *- FL | |
| | | | | | Sub Total (\$\$) | 5,930.00 | 1,935.00 |
| | | | | | - List Item Discount on L Items 10.00/10.00% (\$\$) | 593.00 | 193.50 |
| | | | | | Total Parts (\$\$) | 5,337.00 | 1,741.50 |

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|---------------------|--------------------------------------|----------|---------------------------------|---------------|
| Labour Items | | | | |
| 1 | PANEL KNOCKING | New | 380.00 | 250.00 |
| 2 | SPRAY PAINTING | New | 480.00 | 300.00 |
| 3 | WIRE CHECKING & PROGRAMMING HEADLAMP | New | 160.00 | 20.00 |
| 4 | COMPUTERISED WHEEL ALIGNMENT | New | 150.00 | 0.00 |
| | | | Gross Labour Cost (\$\$) | 570.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >