



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

LIM YEW BOO SPRAY PAINT CO

Ref : CS/TP20006801/Ktf3e2

BLOCK 10, SECTOR C SIN MING ROAD
INDUSTRIAL ESTATE #01-10 SINGAPORE 575645

Date : 03-07-2020



ON BEHALF OF TAN NGEE HUNG

Code : TP155

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	Veh. Inspected	SJR 4960P
Policy No.	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	10/06/2020

2. Vehicle Particulars & Condition

Make & Model	SUBARU IMPREZA (A)	c.c	1994
Engine No.	HIDDEN	Year of Reg.	2007
Chassis No.	GDA020907	Colour	METALLIC BLACK
Odometer	194739	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/40Z R18	PIRELLI	8 mm
L/H Front Tyre	235/40Z R18	PIRELLI	8 mm
R/H Rear Tyre	235/40Z R18	PIRELLI	8 mm
L/H Rear Tyre	235/40Z R18	PIRELLI	8 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION PAINT WORK. THE CAUSE OF THE DAMAGE DUE TO CHEMICAL AGENT. (ACID).

DAMAGES SEE DETAILS.

5. General Information

Accident Date	12/02/2020	Inspection Date	10/06/2020
Survey held at	LIM YEW BOO SPRAY PAINT CO BLOCK 10, SECTOR C SIN MING ROAD INDUSTRIAL ESTATE, #01-10 SINGAPORE 575645.		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**