



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM20006803/Upa3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811

Date : 07-08-2020



ATTN:YVONNE

Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKM 3972B	Veh. Inspected	SLZ 8489S
Policy No.	GA089650	Coverage (\$)	0.00
Claim No.	S0M02Q1F	Excess (\$)	0.00
Assign From		Assign Date	30/06/2020

2. Vehicle Particulars & Condition

Make & Model	SUBARU FORESTER 2.0 (A)	c.c	1995
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	JF1SJ5KC5JG105885	Colour	WHITE
Odometer	47233	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	235/50 R18	YOKOHAMA	7 mm
L/H Front Tyre	235/50 R18	YOKOHAMA	7 mm
R/H Rear Tyre	235/50 R18	YOKOHAMA	7 mm
L/H Rear Tyre	235/50 R18	YOKOHAMA	7 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	28/06/2020	Inspection Date	30/06/2020
Survey held at	ASIA MOTORSPORTS SOLUTION PTE LTD 37A EVERITT ROAD SINGAPORE 428586		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	-----------------------