



**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883 .

ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbro@gmail.com

Invoice/Ref No: YQ1824Y200528

**Estimate**

<b>Customer</b>		
<b>Name:</b> Lonpac Insurance Berhad		<b>Date:</b> 29-06-20
<b>Address:</b> Motor Claims Department		<b>Vehicle No:</b> YQ1824Y
300 Beach Road #17-04 / 07		<b>Model/Make:</b> Mitsubishi
The Concourse	Singapore 199555	<b>Canter:</b> FEB71GR4SDEM

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
	To cut out and refabricate ; realign etc. <i>cracked</i>	\$6,000.00	2500 <i>Local repair</i>
	To putty & spray painting & including touch up paint on accident affected	\$ 800.00	600

Total Parts & Labour of estimate for damaged vehicle	\$6,800.00
------------------------------------------------------	------------

Total amount in Lump Sum Basis for repaired vehicle	
-----------------------------------------------------	--

SDLS: \_\_\_\_\_



M/s Liu's Brother Auto Engrg Wks

*not Authorized  
LKR  
9/2 TOTAL \$3100  
4 days.*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: