

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H

**TAX INVOICE**

NTUC INCOME INSURANCE CO-OPERATIVE LTD INV No. NA2003616
73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSE
SINGAPORE 189556

INV Date 13/07/2020
Reference NS/INC20006812/T1sf3n2
Code INC4

**PROFESSIONAL SERVICE FEE**

Vehicle No. SHD 3793J
Insured Veh. SHC 6159B
Claim No. MT/1095505-002
Policy No.
Accident Date 28/06/2020
Inspection Date 29/06/2020

Description	Total
Survey Inspection	160.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	160.00
GST (7%)	11.20
Grand Total	171.20

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'National Assessment Centre Services'**

National Assessment Centre Services***HYN***




National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC20006812/T1sf3n2				
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date: 13-07-2020	
Code: INC4				
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 6159B	Veh. Inspected	SHD 3793J	
Policy No.		Coverage (\$)	0.00	
Claim No.	MT/1095505-002	Excess (\$)	0.00	
Assign From		Assign Date	29/06/2020	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA PRIUS HYBRID	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JTDKB3FU703569229	Colour	BLUE	
Odometer	316503	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	WEST LAKE	6 mm	
L/H Front Tyre	195/65 R15	WEST LAKE	6 mm	
R/H Rear Tyre	195/65 R15	WEST LAKE	6 mm	
L/H Rear Tyre	195/65 R15	WEST LAKE	6 mm	
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
Accident Date	28/06/2020	Inspection Date	29/06/2020	
Survey held at	COMFORTDELGRO ENGINEERING PTE LTD 59 LOYANG DRIVE SINGAPORE 508969			
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days			



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 3793J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DEFORMED	458.60	458.60
1	REAR BUMPER CENTER-BLACK	DEFORMED	552.60	552.60
1	REAR BUMPER REINFORCEMENT	BENT	318.80	318.80
1	REAR BUMPER EXTENSION RH	TO REPAIR SEE LABOUR	232.00	-
1	REAR BUMPER EXTENSION LH	TO REPAIR SEE LABOUR	232.00	-
1	REAR BUMPER RETAINER RH	NOT NECESSARY	112.70	-
1	REAR BUMPER RETAINER LH	NOT NECESSARY	112.70	-
10	REAR BUMPER CLIPS	NECESSARY	22.00	22.00
1	REAR BUMPER TOW COVER	MISSING	82.70	82.70
1	TAILGATE OUTER GARNISH	TO REPAIR SEE LABOUR	889.70	-
1	TAILGATE HYBRID S	NECESSARY	52.40	52.40
1	TAILGATE PRIUS	NECESSARY	60.80	60.80
1	TAILGATE TOYOTA STAR	NECESSARY	52.90	52.90
	LESS 25% DISCOUNT		-794.98	-400.20
			2,384.92	1,200.60
<u>NETT ITEMS</u>				
1	TAILGATE COMFORTDELGRO (N)	NECESSARY	30.00	30.00
1	TAILGATE 65521111 (N)	NECESSARY	30.00	30.00
1	TAILGATE APPS (N)	NECESSARY	40.00	40.00
1	REVERSE SENSOR (N)	NOT WORKING	135.70	135.70
	LESS 10% DISCOUNT		-23.57	-23.57
			212.13	212.13
<u>SPECIAL NETT ITEMS</u>				
2	REAR FENDER ADV STICKER RH/LH (SN)	NECESSARY	200.00	200.00
1	REAR BUMPER ADV STICKER (SN)	NECESSARY	50.00	50.00
			250.00	250.00

Report Ref No. NS/INC20006812/T1sf3n2



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR BUMPER EXTENSION RH,REAR BUMPER EXTENSION LH AND TAILGATE OUTER GARNISH.		600.00	480.00
	SPRAYPAINT CHARGE.		500.00	400.00
	CHECK ALL LIGHTING.		40.00	30.00
	R/I REVERSE SENSOR.		120.00	30.00
			1,260.00	940.00
GRAND TOTAL			4,107.05	2,602.73
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				2,050.00

Report Ref No. NS/INC20006812/T1sf3n2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H

PHOTOGRAPHS FOR VEHICLE NO. SHD 3793J

INSPECTION





National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H





National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H





National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H





National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H





National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H

PHOTOGRAPHS FOR VEHICLE NO. SHD 3793J

RE-INSPECTION

