

WORTDELDRO ENGINEERING PTE LTD PAIR ESTIMATE*

VEHICLE NO SHA5006B

MAKE :

27/06/20

MODEL HYU- I40

Qty	Parts Description/ Labour	TYPE	CHIANG/NTUC	
			Unit Price	Amount
1	REAR BUMPER COVER			\$1,106.00 de ✓
2	REAR BUMPER BRACKET SIDE LH/RH			
10	REAR BUMPER CLIPS		\$35.60	\$71.20 x nn
1	REAR BUMPER UNDER COVER		\$2.20	\$22.00 ✓
1	BOOTLID CRDI PLATE			\$228.00 B ✓
1	BOOTLID I-40 PLATE			\$27.90 x nn
				\$21.10 x nn
	SUB TOTAL		1128	\$1,476.20
	20.00%			\$295.24
	DISCOUNTED TOTAL		902.40	\$1,180.96
1	BOOTLID COMFORT LOGO			\$30.00 x nn
1	BOOTLID COMFORT TEL NO			\$30.00 x nn
1	REVERSE SENSOR		135.70	\$135.70 ✓
				\$165.70
	Labour Charge			
	Panel Beating			\$540.00 280
	Spray Painting Charge			\$400.00 200
	Remove/refix reverse sensor			\$60.00 30
	Tuff Kote			\$60.00 x nn
	Check Lighting			\$60.00 30
	TOTAL LABOUR		540	\$1,120.00
	ESTIMATE TOTAL		1578.10	
			4/5 1250	\$2,466.66
			2 days.	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No legal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Tan Hin 97495749

-wp'

29/6/20 2pm

US Resurvey after repair

02 - 02 days

Tan Hin @ Khairi