



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

EQ INSURANCE COMPANY LTD
5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEX
SINGAPORE 069110

INV No. AC2007106
INV Date 20/10/2020
Reference CC4/EQI20006820/R1bs3q2
Code EQI



PROFESSIONAL SERVICE FEE

Vehicle No. SKQ 537Z
Insured Veh. SLM 469X
Claim No. DM20HO00947/JT
Policy No. DMPPHQ20-001896
Accident Date 24/06/2020
Inspection Date 01/07/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

EQ INSURANCE COMPANY LTD

Ref : CC4/EQI20006820/R1bs3q2

5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEXSINGAPORE 069110

Date : 20-10-2020



Code : EQI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLM 469X	Veh. Inspected	SKQ 537Z
Policy No.	DMPPHQ20-001896	Coverage (\$)	0.00
Claim No.	DM20HO00947/JT	Excess (\$)	0.00
Assign From	JAIME	Assign Date	30/06/2020

2. Vehicle Particulars & Condition

Make & Model	B.M.W.520I AT	c.c	1997
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	WBA5A320X0D334849	Colour	BLACK
Odometer	46083	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	245/40 ZR19	PIRELLI	6 mm
L/H Front Tyre	245/40 ZR19	PIRELLI	6 mm
R/H Rear Tyre	245/40 ZR19	PIRELLI	6 mm
L/H Rear Tyre	245/40 ZR19	PIRELLI	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	24/06/2020	Inspection Date	01/07/2020
Survey held at	TRANS EUROKARS PTE LTD 12 SUNGEI KADUT AVE SINGAPORE 729648		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	3 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKQ 537Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	REAR BUMPER	DEFORMED	1,628.00	1,628.00
1	SIDE BRACKET RH	SERVICEABLE	269.00	-
1	SIDE BRACKET LH	SERVICEABLE	269.00	-
1	BOOTLID WEATHERSTRIP	NOT NECESSARY	98.00	-
10	REAR BUMPER CLIPS	NECESSARY	600.00	60.00
	LESS 5% DISCOUNT		-	-84.40
			2,864.00	1,603.60
	<u>SPECIAL NETT ITEMS</u>			
1	SUNDRIES (SN)	NECESSARY	50.00	20.00
			50.00	20.00
	<u>LABOUR</u>			
	TO REPLACE REAR BUMPER,BOOTLID WEATHER STRIP & ALL DAMAGE PARTS.TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.		1,200.00	560.00
	TO RESPRAY REAR BUMPER.		600.00	560.00
	TO TRANSFER THE REVERSE SENSORS.		500.00	200.00
	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		250.00	150.00
	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		350.00	250.00
			2,900.00	1,720.00
	GRAND TOTAL		5,814.00	3,343.60
	RECOMMENDED COST OF REPAIRS			3,343.60

Report Ref No. CC4/EQI20006820/R1bs3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKQ 537Z

INSPECTION





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3551 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

S1 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKQ 537Z

RE-INSPECTION

