

**EUROKARS SERVICES**  
**27A TANJONG PENJURU, SINGAPORE 609042**  
**ESTIMATE COST OF REPAIRS**



<b>Insurance Company Ltd</b> Maxwell Road 17-00 Tower Block MND Complex Singapore 069110 <b>ATTN. : MOTOR CLAIMS</b> <b>FAX :</b>		<b>NAME : SEET SER SIN</b> <b>ADDRESS : BEDOK</b> 470721 <b>TEL :</b>		<b>WIP :</b> <b>EXCESS :</b> <b>DATE : 29-Jun-20</b>	
VEH NO :	SKQ537Z	DATE IN :		CONTACT PERSON :	JOBI
CHASSIS NO :		MILEAGE :		TYPE OF CLAIM :	TP
MODEL :	BMW 520i	DATE REG.:		POLICY NO. :	

**NATURE OF WORKS**

S/NO	Parts Description	QTY	REVISED	PRICES
1	REAR BUMPER <i>de -</i>	1		\$ 1,628.00
2	SIDE BRACKET RH <i>?</i>	1		\$ 269.00
3	SIDE BRACKET LH <i>?</i>	1		\$ 269.00
4	BOOTLID WEATHERSTRIP <i>cut X</i>	1		\$ 98.00
5	REAR BUMPER CLIPS <i>new ✓</i>	10		\$ 600.00
6		0		\$ -
	<b>TOTAL PARTS</b> <i>Loss \$9</i>			\$ 2,864.00
				\$ -
	<b>TOTAL PARTS COST</b>			\$ 2,864.00
	<b>Labour Description</b>			
1	TO REPLACE REAR BUMPER, BOOTLID WEATHER STRIP & ALL DAMAGE PARTS . TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.		<i>560</i>	\$ <del>1,200.00</del>
2	TO RESPRAY REAR BUMPER.		<i>560</i>	\$ <del>600.00</del>
3	TO TRANSFER THE REVERSE SENSORS.		<i>200</i>	\$ <del>500.00</del>
4	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		<i>150</i>	\$ <del>250.00</del>
5	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		<i>250</i>	\$ <del>350.00</del>
6	SUNDRIES.		NETT	\$ <i>20</i> <del>50.00</del>
	<b>TOTAL LABOUR</b>		\$ -	\$ 2,950.00
	<b>TOTAL PARTS</b>		\$ -	\$ 2,864.00
	<b>TOTAL</b>		\$ -	\$ 5,814.00
	<b>LESS EXCESS</b>		\$ -	\$ -
	<b>TOTAL AFTER EXCESS</b>		\$ -	
	<b>GST 7%</b>		\$ -	\$ -
	<b>GRAND TOTAL</b>		\$ -	\$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

Resue

Hp 900/100/68

3 days P/P

01/07/2020 @1030

Resy before paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: