

EUROKARS SERVICES
27A TANJONG PENJURU, SINGAPORE 609042
ESTIMATE COST OF REPAIRS



EQ Insurance Company Ltd		NAME : SEET SER SIN		WIP :	
5 Maxwell Road		ADDRESS : BEDOK		EXCESS :	
#17-00 Tower Block		470721		DATE: 29-Jun-20	
MND Complex Singapore 069110		TEL :			
ATTN. : MOTOR CLAIMS					
FAX :					
VEH NO :	SKQ537Z	DATE IN :		CONTACT PERSON :	JOB:
CHASSIS NO :		MILEAGE :		TYPE OF CLAIM :	TP
MODEL :	BMW 520I	DATE REG.:		POLICY NO. :	

NATURE OF WORKS

S/NO	<u>Parts Description</u>			REVISED	PRICES
	QTY				
1	REAR BUMPER	1	0		\$ 1,628.00
2	SIDE BRACKET RH	1	0		\$ 269.00
3	SIDE BRACKET LH	1	0		\$ 269.00
4	BOOTLID WEATHERSTRIP	1	0		\$ 98.00
5	REAR BUMPER CLIPS	10	0		\$ 600.00
6		0	0		\$ -
TOTAL PARTS					\$ 2,864.00
					\$ -
TOTAL PARTS COST					\$ 2,864.00
	<u>Labour Description</u>				
1	TO REPLACE REAR BUMPER, BOOTLID WEATHER STRIP & ALL DAMAGE PARTS . TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.				\$ 1,200.00
2	TO RESPRAY REAR BUMPER.				\$ 600.00
3	TO TRANSFER THE REVERSE SENSORS.				\$ 500.00
4	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.				\$ 250.00
5	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.				\$ 350.00
6	SUNDRIES.			NETT	\$ 50.00

TOTAL LABOUR	\$ -	\$ 2,950.00
TOTAL PARTS	\$ -	\$ 2,864.00
TOTAL	\$ -	\$ 5,814.00
LESS EXCESS	\$ -	\$ -
TOTAL AFTER EXCESS	\$ -	
GST 7%	\$ -	\$ -
GRAND TOTAL	\$ -	\$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE
BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL
BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A
QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED
IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.